# METRIC MOTORS, INC.

EXCHANGE ENGINES FOR MERCEDES-BENZ CARS

www.mercedesengines.net



E-Mail: metricmotors@earthlink.net

800.622.6867



DATE	INVOICE #
9/20/2008	18089

**BILL TO** 

KAI, VICTOR 12012 DEAD INDIAN MEMORIAL ASHLAND, OR 97520 541-488-1424 SHIP TO

JOHN'S AUTO CARE CENTER 3311 BIDDLE RD. MEDFORD, OR 97504 541-858-0745 -- LUIS

P.O. NUMBE	R TERMS	SHIP VIA	SHIP DATE	CORE CONDITION	ORIGIN	IAL ENG.#	NE	W ENGINE #
	PREPAY	UPS	9/24/2008		61	7912	6179	952-10-007058
QTY.	PART#		DESCRIPTION					AMOUNT
	TURBO-LB  CORE CHA  CORE CHA	617-TURBO LONGBLOCK:: 1980 300GD FOR CONVERSION TO TURBO STICKSHIFT // 116 OIL PAN CORE SUPPLIED OUTRIGHT SALE EXTERNAL ASSEMBLY FROM CORE SUPPLIED FROM A TAKE OUT ("AS IS") EXTRA COMPONANTS PROVIDED = NO CHARGE MANIFOLDS / BRACKETS / MISC. HDWR ETC.			6,900.00 600.00 0.00		6,900.00 600.00 0.00	
1	MISC. SHIPPING	REBUILT T	URBO UNIT				0.00	380.00 150.00
			4 ******3811 sale, exempt	\$8,030.00 from sales tax		0.0	0%	0.00
					Tot	al		\$8,030.00

IMPORTANT: CORE CHARGES MAY APPLY. CORE SUBJECT TO INSPECTION.

UPS Freight <sup>s™</sup> Ups	UPGF www.upsfreight.com	2.0	042 659 621		
					COLLECT THIS AMOUNT \$.00
	(800)922-4099	09/25/08	SMV	AD UF	BD
PO# NONE	UPS FREIGHT PHONE NUMBER	PICK UP DATE	ORIG	BL# NONE	
11571173		5 B	MED	ADV CAR	
MEDFORD	OR 97504	CITY RTE/BYD SCAC	DEST	10577626	(818)712-9881
3311 BIDDLE RD		042 659 6	521	CANOGA PARK	CA 91304-4966
		FREIGHT BILL NUM	BER	7630 ALABAMA A	VE.
JOHNS AUTO C	ARE CTR	54921 l	JPGF	STE 1	
			METRIC AUTOMOTIVE		
CONSIGNEE	DELIVERING TRAI	DELIVERING TRAILER		042 659 621	

CHARGES



INVOICE

TEL (770) 965-3311 (866) 58 FAX (678) 960-0032 www.eurotruck-importers.com

P.O. BOX 729 4104 W. WHITE RD., SUITE 101 OAKWOOD, GA 30566 USA TEL (770) 965-3311 (866) 580-3586 FAX (678) 960-0032

Date	INVOICE#	Sales Rep	
10/29/2014	16982	ws	

Bill To

Kaikoo Victor 12012 Dead Indian Memorial RD Ashland, OR 97520 Ship To

John's Auto Kai Victor 3311 Biddle Road Medford, OR 97504

Part Number	Description	Ordered	Shipped	Each	Price
A 460 320 2078 A 601 351 0080 Shipping	SPRING MOUNT	1 1	1 1	220.00 19.50 12.65	220.00T 19.50T 12.65

THANK YOU FOR YOUR BUSINESS!	Subtotal	\$252.15
NO RETURNS WITHOUT RETURN AUTHORIZATION NUMBER 15% RESTOCKING CHARGE ON RETURNED PARTS	Sales Tax (0.0%)	\$0.00
NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS	Total	\$252.15



# 54 Electrical System - Equipment

Removal and installation of bulbs	82 Electrical System - Body Removal and installation, adjustment of headlamps	60 Body Removing and mounting body	Removal and installation of instrumentsand indicator lamp Removal and installation of instrument panel	300 GD Mod. 460.3-2 Mod. 460.3-3	240 GD Mod. 460.3-0 Mod. 460.3-1	280 GE Mod. 460.2-2 Mod. 460.2-3	Wiring Diagrams 230 G Mod. 460.2-0 Mod. 460.2-1
				0.3-2	0.3-0	0.2-2	0.2-0
060	050	780	250 255	300 GD 1984 and later	240 GD 1984 and later	280 GE 1984 and later	230 G 1984 and up 230GE 1984 and up

# 83 Air Conditioning System

Automatic wiring Central locking wiring

Removal and installation of windshield wiper system

670

Removal and installation of engine hood	Removal and installation of front fender	88 Body-Sheet Metal	Webasto auxiliary heater wiring	AC wiring	Removal and installation of heating and ventilation	
350	097				280	

Reproductions or translations, even extractions, and other copying of this microfilm, regardless of type, are not permissible without our explicit written approval.

IMPORT SERV

Siskiyou Import Services Inc.

1713 Siskiyou Blvd. Ashland, OR. 97520

Phone: 541-482-8162 Fax: 541- -

INVOICE

20468

Printed: 04/28/2016

1005

VISA #########2884 SALE BATCH: 888297 INU:000002 AUTH:054055 APR 28, 16

15:20

1980 Mercedes-Benz - 300D -

Lic#: 64567 - OR

Odometer In: 42050

ar: 541-531-9180

VIN#:

		21 . 041-001-01	00		VIII V		
TOTAL		Qty	Sale	Ext	Labor Description	Hours	Ext
	\$250.52	2.00	2.25	4.50	FREE 40 POINT VISUAL INSPECTION Performed inspection: Valve cover is seeping. Trans	0.30	0.00
KAIKO O M VICTOR		6.50	5.99	38.94	- Late Les play in transmission seal is seen	is leaking	ist j at
CUSTON	ER COPY	1.00	0.00	0.00	6mm, OK.		
DPG					Diagnose reverse light not working	0.50	48.79
Engine Oil Filter 85385		1.00	20.33	20.33			ced
Shop Supplies				5.44	Lube, oil, and filter Includes up to 5 quarts premium engine oil, standardrain plug gasket. Iubricate and check chassis. Che and hoses. Check and fill fluid levels(automatic trannot included). Check and adjust tire pressures. Perfinspection. Road test vehicle.	ck air filte ismission form basio	fluid safety
					Repair parking brake, diagnose Repaired cable, adjusted as best as possible.	1.00	97.57
					Get estimate for transfer case removal Remove and reinstall transfer case about 3.5 hours		0.00
					QC TEST DRIVE	0.20	0.00
					CLEAN FRONT, FRONT SIDE, AND REAR WINDOWS. VACUUM FRONT SEATS AND FLOOR. WIPE DASH AND INSTRUMENT CLUSTER.	0.20	0.00

Org. Estimate	3.00	Revisions	51.79	Current Estimate	54.79	Labor:	181.31
Davisian # 1 Drawn	s Fatimala Ama	nert 3:00, Addition ne - () 23 AM, Fritie	ial Coat \$179 à ted by - Shop y	nevised Editions 5479 Parts Author By Hill Mark, Phone 6	\$5.00 Labor \$46.79 Subjet \$0.00 Taxes & Fees amber - Geliular 5415319160	\$3 0000 Authorized Parts:	69,21
						SubTotal:	250.52
						Tax:	0.00
						Total:	250.52
Payments - Visa	****					Bal Due:	\$0.00

Vehicle Received: 4/28/2016

#### MOBIL 1 LUBE EXPRESS/ JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504

Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE 35332

Org. Est. # 065621

Print Date: 01/05/2015

### INVOICE

VICTOR, KAI and ROXANN 1980 Mercedes-Benz - 300GD -

4222 MIDWAY AVE Lic #: SL64567 - OR

Odometer In: 42050 Grants Pass, OR 97527 Odometer Out: 42050 Unit#:

Home 510-517-8476 --- HUSBAND 541-488-1424 Vin #: 46033217004769

Cust ID: 2531				Hat # :	Ref#:
Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
OIL FILTER				LIST	0.00
XXXX	1.00	5.00	5.00	Change Motor Oil & Oil Filter	9.99
MOBIL SPECIAL 5W-30				Drained Motor Oil & Replaced Oil Filter, Added Th	
5W30	7.00	4.00	28.00	Amount of Mobil Special Motor Oil, Lube Chassis,	
WHEEL BEARING NUT	50 <del>.</del>		20.00	Off All Fluids.	
460 990 02 60	4.00	18.00	72.00	FRONT AXLE REPAIR	900.00
AXLE SEAL	4.00	16.00	72.00	REPLACED WHEEL BEARINGS,KING PIN BEAF SEALS,CV BOOTS,DIFFERENTIAL COVER GAS	
W 460	2.00	45.00	90.00	FRONT SUSPENSION	270.00
C/V GREASE		10.00	30.00	REPLACED SPRINGS & SHOCKS	
SL3174	12.00	3.50	42.00	REAR SUSPENSION	720.00
SHOP SUPPLIES	.2.55	3.30	42.00	REPLACED SPRINGS, SHOCKS & WELDED IN 3 LOCATOR BRACKETS	SPRING
SS	1.00	20.00	20.00	DIAG.ELECTRICAL PROBLEM FUSE	135.00
				BLOWN	
				FOUND WIRES FOR HORNS BEHIND FRONT G REPARIED THEM AND ALL WAS OKAY	RILL WAS CUT
				DIAG.BRAKE & ENGINE SHUT OFF	225.00
				PROBLEM	
				REPLACED BRAKE BOOSTER	
				FOUND PLAY IN TRANS OUTPUT SHAFT BEAR OUTPUT SHAFT TO DIFF IS ALSO WITH PLAY BEARING.	

Org Letimate \$	2,516.99 Revisions	\$ 0.00 Current Estimate	\$ 2,516.99	Labor:	2,259.99
				Parts:	257.00
				Sublet:	\$0.00
3311 Biddle Rd	POLICE MANUFACTURES				
fledford ON STA	14			Sub:	2,516.99
PRODUCT GEN BUTTO PENCH	STY PROOF WHOMAN			Tax:	0.00
The same of	TAX 99			Total:	2,516.99
SEON DECESSE	High at Marian			Bal Due:	\$0.00
AUTHO DELDMI					
*DOMESTICAL STREET		SPECIALIZING IN E	MW & MINI / MOBIL 1 OILS		

40 % 15 14 17 If work to be done along with the necessary material and hereby grant you and/or your employees permission described on street, highways or elsewhere for the purpose to testing and/or inspection. An express riedged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by e performed in our shop & cannot exceed the original cost of repair.

		Date	Time
ECH Technician	Donn t of t	The second secon	The second secon

THINK YOU FOR YOUR PURCHESE TOWN! PLEASE COME AGAIN

CUSTOMER COPY

AVS.

CVV Response

APPROVED GETTING

#### MOBIL 1 LUBE EXPRESS/ JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504

Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE

35332

Org. Est. # 065621

#### INVOICE

1980 Mercedes-Benz - 300GD -

Odometer In: 42050

**4222 MIDWAY AVE** 

Lic #: SL64567 - OR

Print Date: 01/05/2015

Grants Pass, OR 97527

VICTOR, KAI and ROXANN

Unit#:

Odometer Out: 42050

Home 510-517-8476 --- HUSBAND 541-488-1424

Vin #: 46033217004769

Ref # .

2 250 00

			Hat # :	Ref#:
Qty	Sale	Extended	Labor Description	Extended
			LIST	0.00
1.00	5.00	5.00	Change Motor Oil & Oil Filter	9.99
7.00	4.00	28.00	Drained Motor Oil & Replaced Oil Filter, Added T Amount of Mobil Special Motor Oil, Lube Chassis Off All Fluids.	he Correct s, Check and Top 900.00
4.00	18.00	72.00	REPLACED WHEEL BEARINGS,KING PIN BEA SEALS,CV BOOTS,DIFFERENTIAL COVER GA	RINGS,AXLE SKET & OIL 270.00
2.00	45.00	90.00	REPLACED SPRINGS & SHOCKS	
12.00	3.50	42.00	REAR SUSPENSION REPLACED SPRINGS, SHOCKS & WELDED IN	720.00 3 SPRING
1.00	20.00	20.00	DIAG.ELECTRICAL PROBLEM FUSE	135.00 GRILL WAS CUT
			REPARIED THEM AND ALL WAS OKAY DIAG.BRAKE & ENGINE SHUT OFF PROBLEM	225.00
			FOUND PLAY IN TRANS OUTPUT SHAFT BEAF	RING,TRANSFER DUE TO
	1.00 7.00 4.00 2.00 12.00	1.00 5.00 7.00 4.00 4.00 18.00 2.00 45.00 12.00 3.50	1.00     5.00       7.00     4.00       28.00       4.00     18.00       72.00       2.00     45.00       90.00       12.00     3.50       42.00	1.00 5.00 5.00  1.00 5.00 5.00  1.00 5.00 5.00  1.00 4.00 28.00  1.00 18.00 72.00  2.00 45.00 90.00  1.00 20.00 20.00  1.00 20.00 20.00  1.00 20.00 20.00  LIST Change Motor Oil & Oil Filter Drained Motor Oil & Replaced Oil Filter, Added TAmount of Mobil Special Motor Oil, Lube Chassis Off All Fluids. FRONT AXLE REPAIR REPLACED WHEEL BEARINGS,KING PIN BEAR SEALS,CV BOOTS,DIFFERENTIAL COVER GAR FRONT SUSPENSION REPLACED SPRINGS & SHOCKS REAR SUSPENSION REPLACED SPRINGS,SHOCKS & WELDED IN LOCATOR BRACKETS DIAG.ELECTRICAL PROBLEM FUSE BLOWN FOUND WIRES FOR HORNS BEHIND FRONT OF REPARIED THEM AND ALL WAS OKAY DIAG.BRAKE & ENGINE SHUT OFF PROBLEM REPLACED BRAKE BOOSTER FOUND PLAY IN TRANS OUTPUT SHAFT BEAF OUTPUT SHAFT TO DIFF IS ALSO WITH PLAY

Org. Estimate	\$ 2,516.99	Revisions	\$ 0.00	Current Estimate	\$ 2,516.99	Labor:	2,259.99
Marine Street,						Parts:	257.00
						Sublet:	\$0.00
						Sub:	2,516.99
						Tax:	0.00
						Total:	2,516.99
						Bal Due:	\$0.00

[ Payments - Cash - \$2,516.99 ]

Signature \_

SPECIALIZING IN BMW & MINI / MOBIL 1 OILS

I have a suthorize the above repair work to be done along with the necessar to use rate the car or truck herein described on street, highways or elsewhen mechanic's lien is hereby acknowledged on above car or truck to secure the vendor. Warranty work has to be performed in our shop & cannot exceed the	amount of repairs thereto	. Warranty on parts is determined by	
vendor. Warranty work has to be pendimed in our shop a carried and are	Dete	Time	

Labore



INVOICE

TEL (770) 965-3311 (866) 58 FAX (678) 960-0032 www.eurotruck-importers.com

P.O. BOX 729
4104 W. WHITE RD., SUITE 101
OAKWOOD, GA 30566 USA
TEL (770) 965-3311 (866) 580-3586
FAX (678) 960-0032

 Date
 INVOICE #
 Sales Rep

 10/24/2014
 16960
 WS


Bill To

Kaikoo Victor 12012 Dead Indian Memorial RD Ashland, OR 97520 Ship To

John's Auto Kai Victor 3311 Biddle Road Medford, OR 97504

Part Number	Description	Ordered	Shipped	Each	Price
A 460 324 0315 Shipping	SPRING MOUNT - REAR AXLE SHIPPING & HANDLING - USPS Medium Flat Rate	2	2	22.75	45.50T 12.00

THANK YOU FOR YOUR BUSINESS!	Subtotal	\$57.50
NO RETURNS WITHOUT RETURN AUTHORIZATION NUMBER 15% RESTOCKING CHARGE ON RETURNED PARTS	Sales Tax (0.0%)	\$0.00
NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS	Total	\$57.50



# INVOICE

DATE: October 30, 2014

INVOICE: 2001

SEND TO: SOLD TO:

John's Auto Care Center 3311 Biddle Rd Medford, OR 97504

541-770-8061

John's Auto Care Center 3311 Biddle Rd Medford, OR 97504 541-770-8061

		QUANTITY	UNIT PRICE, \$		TOTAL
ID	DESCRIPTION		37.8	S	75.60
1	Mercedes W460 Axle Shaft Seal up to Axle 7 023946	2		\$	-
2				\$	-
3				\$	-
4				\$	-
5				\$	-
6	3			\$	-
7				\$	-
8				\$	-
5				\$	-
11	0		SUBTOTAL	\$	75.60
			TAX RATE		
			DISCOUNT		
		SHIPPING	AND HANDLING		9.25
			TOTAL	\$	84.85

At you do not like our product for any reason, within 30 days of receipt of your order, you may return products.

Please read our WARRANY and RETURN policy

# FOURBYFOURCLUB INC. 65 Hemlock Road, Pompton Lakes, NJ 07442 USA

Tel: 201- 258 4778 email: mercedes@fourbyfourclub.com web: www.fourbyfourclub.com

BRAKE BOOSTER 002 430 37 30

<sup>20%</sup> of restocking fees will apply, all applicable sales taxes will be refunded. Shipping charges are non-refundable.

Absolutely no return accepted for any electrical items, special order parts and parts marked inor returnable" in our parts description.

#### JOHN'S AUTO CARE CEN MID# VX41210539001 3311 BIDDLE RD OR 97504 MEDFORD

MERCH

SEO# 003312

OTY PRICE AMOUNT 465.50 TAX 0.00 100分享 建设备线

AUTH# 07445C \*XXXXXXXXXXXXXXX2712 CREDIT SALE

VISA 11/04/13 16:01

CVV Response: M APPROVED 074450

10X1025

MOBIL 1 LUBE EXPRESS/ JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766

Extended

FOREIGN & DOMESTIC AUTO REPAIR

INVOICE

29739

Org. Est. # 059661

Print Date: 11/04/2013

1980 Mercedes-Benz - 300GD -

Lic #: SL64567 - OR

Unit#:

Vin #: 46033217004769

Odometer In: 42050

Odometer Out: 42050

AND 541-488-1424

Qty

Hat #:

**Labor Description** 

Ref#:

Extended

90.00

THANK	YOU FOR YOUR PURCHASE TODAY! PLEASE COME AGAIN	
	CLISTOMER COPY	

13X1145 BELT

1.00	14.50	14.50
2.00	9.50	19.00

Sale

CHECK WHY P/S BELT BROKE 72.00 REPLACED ALL BELTS 0.00 BLEED BRAKES, SOFT PEDAL REAR BRAKE CYLINDERS, SHOES, DRUMS, HARDWARE KITS **NEED REPLACED** 270.00

REPLACE REAR BRAKE WHEEL CYLINDERS, SHOES, HARDWARE KITS & **BLEED BRAKES** 

CK.REAR BRAKE SHOES & ADJUST COMPLETED

DRILL OUT BOLTS FOR SHOE ADJUSTERS & REPLACE BOTH BOLTS

TURN BOTH BRAKE DRUMS

COMPLETED

Current Estimate \$ 465.50 Org Estimate \$ 105.50 Revisions \$ 360.00 Labor: 432.00 Revision# 1, Previous Estimate Amount: 106.50 Additional Cost: 365.55 Revisad Estimate: 465.50, Parts: \$0.00 Labor: \$360.00 Sublet: \$0.00 Taxes & Fees: \$0.00 Authorized by -VICTOR, KAI, Date: 184/2018, Time: 2.59 FM, Indianes By Shirp, Phone Number: Home \$10.517-8476 Parts: 33.50 Sublet: \$0.00 Sub: 465.50 Tax: 0.00 Total: 465.50 Bal Due: \$0.00 [ Payments - Cash - \$465 50 ]

SPECIALIZING IN BMW & MINI / MOBIL 1 OILS

y authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature Written By BRITO, LUIS - Technicians SHOP TECH, Technician, PETERSEN MIC

Page 1 of 1

Date

Copyright (c) 2013 Mitchell Repair Information Company, LLC invhrs 03.18.2011 JD

Time

#### MOBIL 1 LUBE EXPRESS/ JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE 28777 Org. Est. # 058726

INVOICE

1980 Mercedes-Benz - 300GD -

Print Date: 08/27/2013

4222 MIDWAY AVE

000 180 25 09

617 200 18 15

617 203 01 80

82141467704

ANTI-FREEZE COOLANT

Thermostat O-Ring

Lic #: SL64567 - OR

Odometer In: 42050

Grants Pass, OR 97527

VICTOR, KAI and ROXANN

Part Description / Number

MOBIL 15W-40 DEVAC 1300

Unit#:

Odometer Out: 42050

Home 510-517-8476 --- HUSBAND 541-488-1424

Qty

1.00

7.00

1.00

1.00

1.00

Sale

10.02

4.00

28.32

0.92

25.95

Extended

10.02

28.00

28.32

0.92

25.95

Vin #: 46033217004769

Ref#:

Cust ID: 2531

Oil Filter Kit

Thermostat

15W40

Hat #: 1615

**Labor Description** Extended 9.99 Change Motor Oil & Oil Filter Drained Motor Oil & Replaced Oil Filter, Added The Correct Amount of Mobil Special Motor Oil, Lube Chassis, Check and Top

Off All Fluids.

OVERHEATS WHEN IT SITS? PLEASE 0.00 **FLUSH RADIATOR** 

SEE BELOW

R&R THERMOSTAT & FLUSH COOLING 90.00

SYSTEM

REPLACED THERMOSTAT & CHANGED COOLANT, GAUGE NOW DISPLAYS SLIGHTLY OVER 1/2 DURING EXTENDED

IDLE.

Gina
Gina
541-941-4951
Furgusons
Villas @ 62

Org. Estimate	\$ 48.01	Revisions	\$ 145.19	Current Estimate	\$ 193.20	Labor:	99.99
Revision# 1, Previo	ous Estimate An	nount 48.01 Addition	nat Cost 145 19 3 15 PM Initiated	Revised Estimate - 193 20, By - Shop, Phone Number -	Parts: \$55.19 Labor: \$90.00 Sublet: \$0.00 Taxes & Fees: \$0.00 Home 510-517-8476	Parts:	93.21
Tallian Devily 219						Sublet:	\$0.00
						Sub:	193.20
						Tax:	0.00
						Total:	193.20
						Bal Due:	\$0.00
[ Payments - Visa -	\$193.20]						-

SPECIALIZING IN BMW & MINI / MOBIL 1 OILS

y authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission erate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

cindoi. Training is a series of the series o		
Signature	Date	Time

#### MOBIL 1 LUBE EXPRESS/ JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR 23006

Org. Est. # 051433

INVOICE

Print Date: 06/21/2012

VICTOR, KAI and ROXANN

**4222 MIDWAY AVE** 

Grants Pass, OR 97527

Home 510-517-8476 — HUSBAND 541-488-1424

Cust ID: 2531

1980 Mercedes-Benz - 300GD -

Lic #: SL64567 - OR

Odometer In: 41401

Odometer Out : 41401

Vin #: 46033217004769

Hat#

Unit#:

Ref#:

Oddi ID . Loo i				i iai # .	1101 // .
Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
Fan Clutch 000 200 04 22	1.00	150.00	150.00	C/S CHECK THE VALVE ADJUSTMENT, RADIATOR, THERMOSTAT AND THE ELECTRICAL PLUG IN THE FRONT OF	0.00
Valve Cover Gasket				THE VEHICLE	
617 016 01 80	1.00	14.00	14.00	CHECK THE VALVE ADJUSTMENT	170.00
Oil Filter Kit				CHECK AND AJUSTED VALVES TO SPECS	
000 180 25 09	1.00	10.02	10.02	Change Motor Oil & Oil Filter	9.99
MOBIL 15W-40 DEVAC 1300				Drained Motor Oil & Replaced Oil Filter, Added The	Correct
15W40	7.00	4.00	28.00		Check and Top
ANTI-FREEZE COOLANT				Off All Fluids. R&R RADIATOR	102.00
82141467704	1.00	16.89	16.89	REMOVE & REPLACE RADIATORINSTALL NEV	
SHOP SUPPLIES				REPAIR POWER WIRING AROUND	42.50
SS	1.00	7.50	7.50	BATTERY	
CLEAN & REPAIR RADIATOR				REPAIR POWER WIRING AROUND BATTERY	
ADIATOR REPAIR	1.00	48.00	48.00	ODO NO LONGER WORKS.	
				06/21/12	

Org. Estimate	\$ 598.90	Revisions	\$ 0.00	Current Estimate	\$ 598.90	Labor:	324.49
						Parts:	274.41
						Sublet:	\$0.00
						Sub:	598.90
						Tax:	0.00
						Total:	598.90
[ Payments - Cash	\$598.90]					Bal Due:	\$0.00

SPECIALIZING IN BMW & MINI / MOBIL 1 OILS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to prate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Written By BRITO, LUIS - Technicians SHOP TECH, Technician, LOROS, DEAN 9/

Page 1 of 1

Date

Copyright (c) 2012 Mitchell Repair Information Company, LLC invhrs 11.18.10 JD

Time

#### MOBIL 1 LUBE EXPRESS / JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE 19347 Org. Est. # 046981

INVOICE

1980 Mercedes-Benz - 300GD -

Lic#: SL64567 - OR

Odometer In: 41078 Odometer Out: 41078

Print Date: 08/19/2011

Unit#:

Hat # :

**Labor Description** 

Vin #: 46033217004769

Ref#:

Extended

Home 510-517-8476 --- HUSBAND 541-488-1424 Cust ID : 2531

Qty

Part Description / Number MOBIL 15W-40 DEVAC 1300 15W40

VICTOR, KAI and ROXANN

Grants Pass, OR 97527

4222 MIDWAY AVE

7.00 4.00 28.00

Extended

Sale

CUST STS LEAKS FROM ENGINE ADVISE 42.50 STUD PULLED OUT OF OIL FILTER HOUSING. HELICOIL STUD HOLE, INSTALL NEW STUD & CHECK. CLEANED TOP OF

ENGINE. USED 7 QTS 15-40 TO REFILL MILEAGE & ODO NOT WORKING

JOHNS AUTO CARE CENTER 2311 BIDDLE RD MEDFORD, OR 97584 541-858-8745

HOST HAME: HOUA DLRM 8815654836 TIDE OF EXP 85/14 MISA HARBE \$70.50

CUSTOMER COPY

[Payments Cash - \$70 50]

Correct Estimate \$ 70.50 Org Estimate \$70.50 Revisions \$ 0.00 Labor: 42.50 Parts: 28.00 Sublet: \$0.00 Sub: 70.50 Tax: 0.00 Total: 70.50 Bal Due:

SPECIALIZING IN BMW & MINI / MOBIL 1 OILS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission rate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express nic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

Witten By BRITO LUIS Technicians SHOP TECH Technician LOROS DEAN 9.

Page 1 of 1

Date

Time Copyright (c) 2011 Mitchell Repair Information Company, LLC invhrs 1118 10 JD

\$0.00

#### MOBIL 1 LUBE EXPRESS / JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE 18378

Org. Est. # 045894

INVOICE Print Date: 06/17/2011 1980 Mercedes-Benz - 300GD -VICTOR, KAI and ROXANN Lic #: SL64567 - OR **4222 MIDWAY AVE** Odometer In: 40998 Odometer Out: 40998 Grants Pass, OR 97527 Unit #: Home 510-517-8476 --- HUSBAND 541-488-1424 Vin #: 46033217004769 Ref# Cust ID: 2531 Hat #: Part Description / Number **Extended** Qtv Sale Extended **Labor Description** Valve Cover Gasket C/S THE TRANSFER CASE WILL NOT 0.00 STAY IN GEAR. 617 016 01 80 1.00 6.38 6.38 WILL NEED REBUILT TRANSFER CASE MOBIL 15W-40 DEVAC 1300 170.00 CHECK THE VALVE ADJUSTMENT 15W40 8.00 4.00 32.00 VALVE ADJUSTMENT -- ALL VALVES WERE TIGHT. ALSO OIL FILTER FOUND LINE ON TURBO BROKEN--REPAIRED XXXX 1.00 10.00 10.00 9.99 Change Motor Oil & Oil Filter Drained Motor Oil & Replaced Oil Filter, Added The Correct Amount of Mobil Special Motor Oil, Lube Chassis, Check and Top Off All Fluids. HOST NAME: HOUA DLR# 8015654836 TID# 88 XXXXX2012 UISA MISCELLANEOU TOTAL \$228.37 AUS RESPONSE: N CUSTOMER COPY

Revisions \$ 0.00 Current Estimate \$ 228.37 Org. Estimate \$ 228.37 Labor: 179.99 Parts: 48.38 Sublet: \$0.00 Sub: 228.37 Tax: 0.00 Total: 228.37 **Bal Due:** \$0.00 [ Payments - Visa - \$228 37 ]

SPECIALIZING IN BMW & MINI / MOBIL 1 OILS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission rate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express anic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Date

Whiten By ERITO, LUIS - Technicians SHOP TECH, Technician, LOROS, DEAN 9/

Page 1 of 1

#### JOHNS AUTO CARE CENTER INC

3311 BIDDLE RD Medford, OR. 97504

Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE 9760 Org. Est. # 022910

INVOICE

Print Date: 04/22/2009

1980 Mercedes-Benz - 300GD

VICTOR, KAI ROXANN

**4222 MIDWAY AVE** 

Grants Pass, OR 97527

Home 510-517-8476 --- Spouse 541-488-1424

Unit #:

Lic #: SL64567

Odometer In: 38534

Odometer Out: 38534

Vin #: 46033217004769

Cust ID: 2531 Ref#: Hat #:

				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
OIL FILTER		45.00	1500	15W-40 OIL AND FILTER CHG	6.05
7 QTS 15W-40 MOBIL	1.00	15.00	15.00	7 QTS 15W-40 OIL AND FILTER CHG TOPPED OFF ALL FLUIDS	
XXXX	8.00	2.70	21.60	CHECK ALTERNATOR	79.00
Alternator 65amp - Remanufactured AL 117 X	1.00	171.59	171.59	ALT IS BAD, REPLACED ALTERNATOR WITH BOSCH EXCHANGE.	

ANO LAW CLASS 3311 BIDDLE I AD MEDFORD OR 97504 541-858 074

COPY 04/22/2009 17 15 30 Sale:

Transaction # 1 Card Type \*\*\*\*\*2712 Acc:

Entry: Manual 293.24 Total:

Reference No. 00000007 1 ( Auth Code 1. 系持 Respon

address CUL Resp.

DETOMER COFY

n; LOROS, DEAN 9/19/57 ]

ns \$250,59 Current Estimate \$ 280,54 Additional Cost **Revised Estimate** Labor: 85.05 \*\*\*\*\*\* \$250.59 \$280.54 Parts: 208.19 anes & Face \$0.00 Sublet: 0.00 Sub: 293.24 Tax: 0.00 Total: 293.24 **Bal Due:** \$0.00

SPECIALIZING IN BMW

work to be done along with the necessary material and hereby grant you and/or your employees ck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An cknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is vork has to be performed in our shop & cannot exceed the original cost of repair.

Date...... Time.....

Written By: Brito, Luis

Page 1 of 1

01.17.07 Copyright Mitchell 1 Invoic1

#### JOHNS AUTO CARE CENTER INC

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

1980 Mercedes-Benz - 300GD

Vin #: 46033217004769

Lic #: SL64567

Unit #:

Hat #:

Labor Description

3.0 5CYL TURBO (1984 300TD)

INVOICE

9354

Org. Est. # 020196

Print Date: 02/18/2009

Odometer In: 37846

Extended

Odometer Out: 37846

431253996885 JOHN'S AUTO CARE CNTR 3311 BIDDLE ROAD RD OR 97504 58-0745

COP 02/18/2009 18:55-04 Sale:

Transaction # Card Type UISA Acc: ининининини 2712

Entry Surped Total:

Reference No

Auth.Code:

Respon.

3551.23

e 541-488-1424

Qty

Ref#:

Sale Extended

80000000 03127B APPROVED

CUSTOMER COPY

[ Technicians : SHOP TECH, Technician; LOROS, DEAN 9/19/57]

**Revised Estimate** Org. Estimate \$3,551.23 Revisions \$0.00 Current Estimate \$ 3,551.23 **Additional Cost** Labor: 2.345.15 Parts: 692.66 Sublet: 513.42 Sub: 3.551.23 Tax: 0.00 Total: 3,551.23 [ Payments - Visa - \$3551.23 ] Bal Due: \$0.00

SPECIALIZING IN BMW

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees ission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date...... Time.....

# **JOHNS AUTO CARE CENTER INC**

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE

9354

Org. Est. # 020196

INVOICE

VICTOR, KAI

**4222 MIDWAY AVE** 

Grants Pass, OR 97527

ROXANN

1980 Mercedes-Benz - 300GD

3.0 5CYL TURBO (1984 300TD)

Lic #: SL64567

Odometer In: 37846

Unit #:

Odometer Out: 37846

Print Date: 02/18/2009

Vin #: 46033217004769

Home 510-517-8476 ---- Spouse 541-488-1424

Cust ID:	2531	Re	of #:		Hat #:	Extended
Part Description /	Number	Qty	Sale	Extended	Labor Description	12.00
Oil Filter Kit					FUEL CHARGE	12.00
617 180 00 09		1.00	10.42	10.42	FUEL CUT FOR	156.00
Accessory Drive B	elt				REMOVE FUEL TANK AND SEND OUT FOR	
10 X 1035		2.00	8.04	16.08	CLEANING REMOVED AND INSTALLED FUEL TANK	
ENG OIL 15W-40			200		REMOVED AND INSTALLED TO BE	50.00
MOBIL 15W-	40	7.00	2.10	14.70	FUEL TANK CLEAN OUT REMOVED FUEL TANK AND SENT TO D&T	
Release Bearing			<b>71.00</b>	71.00	RADIATOR FOR CLEAN OUT.	
000 250 68 15	5	1.00	71.00	71.00	SHIPPING FLYWHEEL TO METRIC MOTORS	26.92
Pressure Plate		1.00	210.00	210.00	SHIPPING CHARGE UPS	. 15
001 250 42 0	4	1.00	210.00	210.00	Oil and Filter Change	5.15
Header Pipe 123 490 17 2	0	1.00	174.00	174.00	Changed Motor Oil & Replaced Filter, Added 8	
mostat with					QTS Premium Motor Oil, Lube Chassis, Check all	
617 200 18		1.00	23.91	23.91	Fluid Levels	
Water Pump				110.00	LONG BLOCK - Remove & Replace - [Consists of	2,184.00
110 200 17		1.00	110.00	) 110.00	cylinder block fitted with pistons, rings, connecting	
Water Pump Ga		1.00	1.02	2 1.02	rods crankshaft and all bearings, cylinder heads,	
616 201 00		1.00	1,02		camshaft, timing chain and sprockets. Includes: Clean	
Coolant/Antifre		3.00	12.60	6 37.98	and transfer fuel and electrical assemblies, engine	
INTAKE HOS					CUSTOM INSTALLATION OF 300TD ENGINE	
21767.GA		1.00	23.5	5 23.55	INTO 300GD SUV,CUSTOM INSTALL INJECTION LINES,GLOW PLUG	
					CIRCUT, ALTERNATOR, AUX VACUUM PUMP	
					AND CONNECTIONS, CUSTOM ENGINE OIL	
					LINES AND SENDING UNIT	
					ADAPTER, CUSTOM INSTALL INTAKE	
					SYSTEM.	57.00
					TOW CHARGE TOWING TO MUFFLER SHOP	37.00
					EXHAUST WORK	367.50
					EATIAGGT WORK	



CUSTOM EXHAUST

MEDFORD, OR 97504 805488851 324193495995

TERMINAL ID: MERCHANT #:

INVOICE: 088337 TIME: 14:01 AUTH NO: 036410

TOTAL

\$40.39

CUSTOMER COPY

- MEDFORD 97504 LAKE AVENUE 99018

FLUID CONNECTOR PRODUCTS 4900 CRATER LAKE AVENUE PHONE 541 779-4124 MEDFORD, OR 97504 541 773-7060

INVOICE/PACKING LIST

ORDER NO. M 20474

CASH SALES - MEDFORD

I. 4900 CRATER LAKE AVENUE

P MEDFORD, OR 97504

0 н

40.39	TOTAL	ORDER TOTAL						
40.39	SUB TOTAL	SUB		**	*			
5.41	5.41		14	10343-8-8 MALE JIC	103 M	1	1	ω
5.90	5.90		<b>VEL</b>	10643-8-8 FEMALE JIC SWIVEL	106	р	Ъ	2
29.08	29.08	2	7543-15-8 FEMALE METRIC L SWIVEL 90 EL BALL NOSE	1C543-15-8 FEMALE METRIC I	1C5	Н	н	Ъ
TADOMY	PRICE	TP UNIT PRICE	DESCRIPTION			QTY SHIP	QTY ORD	LINE #
488-1424	KAI	VISA	COUNTER SALE	1/08/2009 85	1/08/2009			VISA
PHONE #	AS GENEGRAD	CASH SALE	SHIPPED VIA	DATE SHIPPED SLSM	REQ SHIP DATE		CUSTOMER ORDER NO	CUST
1 OF 1	PAGE 1 OF		**VISA**			- Productive to beag to	PRESTANDA BEAR STORMS IN TACKOR METERS AND THE SECONDS	and the same same

NO. OF CINS. ALL RETURNS MUST BE AUTHORIZED BY SELLER IN ADVANCE AND A RESTOCKING CHARGE WILL BE APPLIED. WEIGHT SIGNATURE: PULLER ID

PRINT NAME:

431253996885 IOHN'S AUTO CARE CNTR 311 BIDDLE ROAD DFORD OR 97504 041 -858 -0745

#### JOHNS AUTO CARE CENTER INC

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

Ref#:

Sale Extended

Qty

INVOICE

6663

Org. Est. # 015276

Print Date: 12/26/2007

Odometer In: 30385

COPY 12/26/2007 18:14:53 Sale:

Transaction # UISA Card Type Swiped Entry 117.00 Total

00000003 Reference No -036380 Auth Code: APPROVED Respon

CLISTOMER COPY

1980 Mercedes-Benz - 300GD

DIESEL

Lic #: SL64567

Unit #:

Vin #: 46033217004769

KILL SWITCH WAS NOT REBUILT

CORRECTLY---TECH REPAIRED ALL CHK GOOD----TECH CLEANED MAIN FUSE AND CONTROL RELAY-----NEEDS GLOW PLUGS

ALL REMOVED -- TESTED AND CLEANED

Hat #:

Odometer Out: 30385

Extended Labor Description 117.00 CUST STS ENG WILL NOT TURN OFF -- TECH INSP FOUND VAC SYSTEM FOR THE

[ Technicians | LOROS, DEAN 9/19/57]

Org. Estimate \$117,00	Revisions \$8.00	Current Estimate	\$ 117.00	Additional Cost	Revised Estimate	Labor:	117.00
						Parts:	0.00
						Sublet:	0.00
8						Sub:	117,00
						Tax:	0.00
I Daymanta Mica S117.00						Total:	117.00
[ Payments - Visa - \$117.00	1					Bal Due:	\$0.00
		SPECIA	FFING IM	RMW			THE RESIDENCE OF THE PARTY OF T

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees rmission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An spress mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE.....

Date...... Time.......

Page 1 of 1

01.17.07 Copyright Mitchell



P.O. BOX 729 4104 W. WHITE RD., SUITE 101 OAKWOOD, GA 30566 USA TEL (770) 965-3311 (678) 414-6647 FAX (678) 960-0032

# INVOICE

Date 11/17/2008 INVOICE # 5185

Sales Rep WS

Bill To

Kaikoo Victor 4222 Midway Ave Grants Pass, OR 97527 Ship To

John's Auto Kai Victor 3311 Biddle Road Medford, OR 97504

Part Number	Description	Ordered	Shipped	Each	Price
Part Number A 001 295 6807 F hipping	Description  CLUTCH SLAVE CYLINDER, 4-SPEED SHIPPING, PACKAGING, INSURANCE  PAYMENT PROCESSED TO VISA XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Ordered 1	Shipped 1.00	42.50 8.25	Price 42.50T 8.25

5	THANK YOU FOR YOUR BUSINESS!	Subtotal	\$50.75
I	NO RETURNS WITHOUT RETURN AUTHORIZATION NUMBER 15% RESTOCKING CHARGE ON RETURNED PARTS	Sales Tax (0.0%)	\$0.00
P	NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS	Total	\$50.75



INVOICE

P.O. BOX 729 4104 W. WHITE RD., SUITE 101 OAKWOOD, GA 30566 USA (678) 960-0032 www.eurotruck-importers.com TEL (770) 965-3311 (678) 414-6647

Date	10/22/2008	INVOICE #	5078
		Sales Rep	WS

Bill To

Kaikoo Victor 4222 Midway Ave Grants Pass, OR 97527 Ship To

John's Auto Kai Victor 3311 Biddle Road Medford, OR 97504

Part Number	Description	Ordered	Shipped	Each	Price
A 009 250 2303 80 Shipping	CLUTCH DISC SHIPPING, PACKAGING, INSURANCE	1	1.00	125.50 14.25	125.50T 14.25

THANK YOU FOR YOUR BUSINESSI	Subtotal	\$139.75
NO RETURNS WITHOUT RETURN AUTHORIZATION NUMBER 15% RESTOCKING CHARGE ON RETURNED PARTS	Sales Tax (0.0%)	\$0.00
NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS	Total	\$139.75



www.mercedesengines.net

NOICE

7630 Alabama Ave. Canoga Park, CA 91304 818.712.9881 Fax 818.712.9932

E-Mail: metricmotors@earthlink.net

800.622.6867

\$8,030.00

DATE	INVOICE#
9/20/2008	18089

BILL TO


KAI, VICTOR 12012 DEAD INDIAN MEMORIAL ASHLAND, OR 97520 541-488-1424 SHIP TO

JOHN'S AUTO CARE CENTER 3311 BIDDLE RD. MEDFORD, OR 97504 541-858-0745 -- LUIS

**Total** 

P.O. NUME	BER TERMS	SHIP VIA	SHIP DATE	CORE CONDITION	ORIGIN	IAL ENG.#	NE	W ENGINE #
	PREPAY	UPS	9/24/2008		61	7912	6179	952-10-007058
QTY.	PART#		DESC	CRIPTION		UNIT PRI	CE	AMOUNT
	CORE CHA	FOR CON STICKSHI CORE SUP EXTERNAL FROM A TA EXTRA CO	VERSION TO IFT // 116 OU PLIED OUTR L ASSEMBLY AKE OUT ("L MPONANTS	L PAN LIGHT SALE FROM CORE SUPP	HARGE		0.00	6,900.00 600.00 0.00
	MISC. SHIPPING	REBUILT TONE WAY	TURBO UNIT SHIPPING C	HARGE	Dic.	7000000	0.00	380.00 150.00
			A ******3811 sale, exempt	\$8,030.00 from sales tax		0.0	0%	0.00

MPORTANT: CORE CHARGES MAY APPLY. CORE SUBJECT TO INSPECTION.



#### WARRANTY

Metric Motors, Inc. warrants to the original purchaser that each engine sold by Metric, under normal use and with periodical maintenance as set forth by the original manufacturer and as listed below shall be free from any defects in materials and workmanship, subject to the following terms and conditions.

Commencing on date of delivery:

12 months unlimited mileage SHORTBLOCKS

LONGBLOCKS

18 months unlimited mileage PRE 1974

3 years or 36,000 miles 1974-1982 3 years or 36,000 miles

Type 601, 602, 603 4 years or 50,000 miles 1983 - Current

Under the terms of this warranty it is our option to repair or replace the engine without charge to the original owner. All warranty repairs must be preauthorized by Metric Motors. Labor claims on authorized repairs will be paid at 80% of the Motor or Mitchel Repair Manuals at an hourly rate not to exceed \$55/hour to a maximum of \$1,500. It is the sole responsibility of the installer to order the proper engine for a specific car and to verify proper application before installing said engine.

#### LIMITED LIABILITY

The liability of Metric under this warranty is limited solely to the repair or replacement of defective parts or workmanship. Metric shall not be liable for any incidental, special, consequential, or exemplary damages, rental cars, or for any service not expressly provided for herein, relating to or arising from the Metric Engine.

#### LIMITATIONS

This warranty applies only to the parts supplied, engine assembly, or shortblock and internal components of the engine. This warranty shall not apply to or include any of the following:

Water Pump (one year warranty)

Injection Pump and Nozzles (2 years or 24,000 miles)(Contamination excluded)

- A. Damage as result of overheating, tack of lubrication, oll viscosity or contamination issues, engine management, faulty carburetion or fuel injection problems (unless installed by us) will definitely VOID warranty. Damage resulting from internal corrosion/contamination from cooling system will definitely VOID warranty.
- B. Repair or replacement required as a result of any accident or misuse.
- C. Any engine used for competition, racing or related purposes.
- D. Any faulty accessory or service item, including all components of the cooling, fuel, electrical and engine controls system and all points, plugs, oil filter, belts & hoses.
- E. Any Metric Engine which has been repaired or remodeled by any person other than an authorized repair facility, or to which any device or accessory not conforming to original manufacturer's specifications has been installed.
- F. Any engine on which the periodic maintenance services required by the original manufacturer have not been performed, including. after engine reaches operating temperature, retorqueing of head bolts as required and readjusting valve clearance. In addition, oil and oil filter must be changed within the first 500 miles and within every 3,000 miles thereafter.

This warranty is given in lieu of all other warranties, expressed or implied, including any warranty of merchantability or fitness for a particular purpose on the part of Metric or the dealer installing the engine. No dealer, nor any agent or employee, thereof, is authorized to extend or enlarge this warranty.

All warranty claims must be accompanied by Engine Block & Serial #, Installers Original invoice & Warranty Repair Invoice. If any new parts installed, we must receive old parts.

#### CORE POLICY

Cores are a valuable component in the running of our business. Obviously we are unable to have engines available on an exchange basis without them, consequently, unless prior arrangements have been made, we must insist on collecting a core deposit. We highly recommend that the installing garage collect a core deposit from the car owner. (at least a check to hold and then void upon Metric's acceptance of the core). The fact that a car came in running does not constitute a rebuildable core. The block may already be at the last repair stare or the head at minimum thickness, etc. Metric reserves the right to determine core viability. Any core determined to be not repairable may be returned to the customer - if they so request - within 14 days of defective core notification. We charge only for those non-repairable important core items as laid out on price list or at time of order. Core items that are repairable, yet require excessive and out of the ordinary repairs (ie: numerous sleeves, special crack repairs, major combustion chamber rebuild, etc.) subject to a 50% core item value charge. Although core charges may apply only for block or head, etc. we must still receive all components relating to those that were supplied. It is the installers responsibility to remove any hardware not included in exchange engine and drain the engine core of oil and water. TO RECEIVE FULL CREDIT, CORES MUST BE RETURNED WITHIN 60 DAYS.



VISA

#### SHIPPING

We deliver engines within Los Angeles, Orange, and Ventura counties for no charge, Any engines that require shipment are done so at customer's expense, including return of core. Freight charges are guaranteed when prepaid at time of order, Prices available upon request. Example of ROUND TRIP rates...California \$150,00, Oregon or Texas \$250,00, New York or Florida \$400,00.



FOB LOS ANGELES



INVOICE

P.O. BOX 729 4104 W. WHITE RD., SUITE 101 TEL (770) 965-3311 (866) 58 FAX (678) 960-0032 www.eurotruck-importers.com OAKWOOD, GA 30566 USA TEL (770) 965-3311 (866) 580-3586

Date	INVOICE#	Sales Rep
6/11/2014	16344	WS

#### Bill To

Kaikoo Victor 12012 Dead Indian Memorial RD Ashland, OR 97520

#### Ship To

Kaikoo Victor 12012 Dead Indian Memorial RD Ashland, OR 97520

- Constitution	Part Number	Description	Ordered	Shipped	Each	Price
	AXLE SVC KIT	W460 FRONT AXLE SERVICE KIT,	1	1	449.50	449.50T
	hipping	COMPLETE SHIPPING & HANDLING - UPS Ground			23.28	23.28

	THANK YOU FOR YOUR BUSINESS!	Subtotal	\$472.78
	NO RETURNS WITHOUT RETURN AUTHORIZATION NUMBER 15% RESTOCKING CHARGE ON RETURNED PARTS	Sales Tax (0.0%)	\$0.00
Ī	NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS	Total	\$472.78



INVOICE

P.O. BOX 729 4104 W. WHITE RD., SUITE 101 TEL (770) 965-3311 (866) 58 FAX (678) 960-0032 www.eurotruck-importers.com OAKWOOD, GA 30566 USA TEL (770) 965-3311 (866) 580-3586

Date	INVOICE#	Sales Rep	
10/6/2014	16872	WS	

Bill To

Kaikoo Victor 12012 Dead Indian Memorial RD Ashland, OR 97520

Ship To

Kaikoo Victor 12012 Dead Indian Memorial RD Ashland, OR 97520

Part Number Description Each Price Ordered Shipped B46-0504-H1 197.00 394.00T BILSTEIN FRONT HD SHOCK, W460 2 2 B46-0514-H1 BILSTEIN REAR HD SHOCK, W460 2 348.00T 2 174.00 460 321 0504 FRONT SPRING, RED, SACHS 2 2 141.25 282.50T A 460 324 0504 REAR SPRING, WHITE, HD 2 2 160.00 320.00T A 002 094 2304 AIR FILTER 35.50 35.50T SHIPPING & HANDLING - UPS Ground 109.41 Shipping 109.41

THANK YOU FOR YOUR BUSINESS!

NO RETURNS WITHOUT RETURN AUTHORIZATION NUMBER 15% RESTOCKING CHARGE ON RETURNED PARTS NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS

Subtotal	\$1,489.41
Sales Tax (0.0%)	\$0.00
Total	\$1,489.41

#### MOBIL 1 LUBE EXPRESS/ JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504 Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

INVOICE

30801

Org. Est. # 061198

JOHN'S AUTO CARE CEN MIDH VX41210539001 3312-DIDDLE RD OR 97504 PRODUCT OTY PRICE AMOUNT GENERAL MERCH 208.98 0.00 SEQ# 004110 101A \$ 208.9E AUTH# 06235C XXXXXXXXXXXXXX2712 CREDIT SALE 02/06/14 16:41 APPROVED 06235C

1980 Mercedes-Benz - 300GD -

Print Date: 02/06/2014

Lic #: SL64567 - OR

Odometer In: 42050

Unit#:

Hat#:

Vin #: 46033217004769

Ref#:

THANK YOU FOR YOUR PURCHASE TODAY!

PLEASE COME AGAIN	Qty	Sale	Extended
CUSTOMER COPY	Securior In County Section 4.	MAN DOMESTIC STATE OF THE	HEAVING CHARLES AND SHE SHOW
#	1.00	48.00	48.00
HOSE CLAMP			
#	2.00	1.50	3.00
ANTI-FREEZE COOLANT			
82141467704	0.50	25.95	12.98
INJECTOR HOSE			
#	1.00	10.00	10.00

BAND 541-488-1424

1	Labor Description	Extended
	CUST STS POS FUEL BACK OF	135.00
)	ENGINEADVISE REPLACED HEATER HOSE FROM CYLINDERHEAD T	0
)	HEATER VALVE REPLACED FUEL INJECTOR RETURN HOSES	

Org. Estimate \$ 208.98

Revisions

\$ 0.00

Current Estimate \$ 208.98

Labor: Dorts:

[ Payments - Visa - \$208 98 ]

SPECIALIZING IN BMW & MINI /

by authorize the above repair work to be done along with the necessary mat to operate the car or truck herein described on street, highways or elsewhere for II mechanic's lien is hereby acknowledged on above car or truck to secure the amou vendor. Warranty work has to be performed in our shop & cannot exceed the original

Signature

Page 1 of 1

#### MOBIL 1 LUBE EXPRESS/ JOHNS AUTO CARE

3311 BIDDLE RD Medford, OR. 97504

Phone - 541-858-0745 Fax - 541-858-0766 FOREIGN & DOMESTIC AUTO REPAIR

30661 Org. Est. # 06100

INVOICE

Print Date: 01/27/2014

Odometer In: 42050

VICTOR, KAI and ROXANN

4222 MIDWAY AVE

Grants Pass, OR 97527

Home 510-517-8476 --- HUSBAND 541-488-1424

Cust ID: 2531

1980 Mercedes-Benz - 300GD -

Lic#: SL64567 - OR

Unit#:

Vin #: 46033217004769

Hat#:

Ref#

Cust ID . 2001				riat ir ,	Rei#:
Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
Oil Filter Kit			.4	Change Motor Oil & Oil Filter	9.99
000 180 25 09	1.00	10.02	10.02	Drained Motor Oil & Replaced Oil Filter, Added The Co Amount of Mobil Special Motor Oil, Lube Chassis, Che	
MOBIL 15W-40 DEVAC 1300	7.00	4.00	28.00	Off All Fluids.	on and Top
15W40	7.00	4.00	26.00	LOSS OF POWER AT TIMES	0.00
GASKET	4.00	4.00	4.00	SEAMS OK	
616 184 07 80	1.00	4.00	4.00	R&I OILFILTER HOUSING	270.00
GASKET			*	INSTALLED 2 HELICOILS FOR OIL FILTER LID STU	
617 184 01 80	1.00	5.00	5.00	REPLACED FLANGE GASKET & BACK COVER GAS	KET

Org. Estimate	\$ 48.01	Revisions	\$ 324.00	Current Estimate	\$ 372.01	Labor:	279.99
				Revised Estimate - 372.01   By - Shop, Phone Number -	Parts: \$9.00 Labor: \$315.00 Sublet: \$0.00 Taxes & Fees: \$0.00 Home 510-517-8476	Parts:	47.02
4 1						Sublet:	\$0.00
						Sub:	327.01
						Tax:	0.00
						Total:	327.01
Payments - Visa -	\$327.01.1					Bal Due:	\$0.00
		The second secon	5	PECIALIZING IN	BMW & MINI / MOBIL 1 OILS		

I was authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permis	sion
to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express	
mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is determined by	
vendor. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.	

Signature		Date	Time
			All III

7630 Alabama Ave. Canoga Park, CA 91304 818.712.9881 Fax 818.712.9932 E-Mail: metric@mercedesengines.net

Nationwide toll free: 800.622.6867

# **IMPORTANT**

RE: FUEL DELIVERY / ENGINE MANAGEMENT

PARTICULARLY ON

MECHANICAL FUEL INJECTION

230SL - 250SE/SL - 280SE/SL

CARBURETOR TYPES

190SL - 220S - 250S - 280S

DIESEL AND V-8 ENGINES

U.S. AND EUROPEAN VERSIONS

IT IS IMPERATIVE THAT, UPON INSTALLATION, THE FUEL INJECTION/CARBURATION AND IGNITION SYSTEMS ARE SET UP CORRECTLY. THROTTLE LINKAGE AND CONTROL RODS MUST BE ADJUSTED PROPERLY


THESE ENGINES ARE SENSITIVE TO IMPROPER FUEL DELIVERY.
AN ENRICHED CONDITION WILL THIN OIL LUBRICATION
PROPERTIES WITHIN THE COMBUSTION AREA RESULTING IN
DAMAGE TO PISTONS, RINGS, AND THE CYLINDER WALL
FINISH. BEARING DAMAGE MAY ALSO OCCUR. INCORRECT
IGNITION PERFORMANCE WILL HAVE SIMILAR RESULTS. THIS IS
ESPECIALLY TRUE WHEN THE ENGINE IS NEW, AS THE
BEARINGS AND PISTON TO CYLINDER WALL CLEARANCE IS AT
A MINIMUM = EXACT TOLERANCE.

DAMAGE TO ENGINE AS A RESULT OF IMPROPER FUEL DELIVERY OR IGNITION RELATED FAILURES, WILL DEFINITELY VOID WARRANTY.

THANK YOU FOR YOUR COOPERATION. IT IS OUR GOAL THAT BOTH YOU AND THE CAR OWNER ARE COMPLETELY SATISFIED.

METRIC MOTORS, INC.

)pen Daily .00 am - 5:00 pm





Phone: 476-6944

502 Union Avenue • Grants Pass, Oregon 97527

CUSTOMER'S ORDER NO.	PHONE NO.	12-	12-17	
SOLD TO Kalk	Victor		, 20 ,	
ADDRESS				
CITY				
SOLD BY CASH C	O.D. CHARGE ON ACCT, MDSE. RETD.	PAID OUT		
QUANTITY	DESCRIPTION	PRICE	AMOU	NT
, 1 Taul 1	ight consister 1			
2 1 7 ma	1		75	מל
1 724	Adapter			
	7 1			
5	_ ^			
6	$\Delta \Pi$			
7				
6	KV.			
9	11.1156			
10	0 11 11			
11	V			
10				
The Vendor expressly reso until full and final payment	erves title to merchandise billed herein	TAX		
Accounts due 10th of n	nonth following purchase. FINANCE a "PERIODIC RATE" of 11/1/2 PER	TOTAL	75	00
to the past due balance.	ERCENTAGE RATE OF 18% applied			
1	Thank You			
1	ECID X		>	
	BY X			

Darren Williamson's Auto Body 1120 ORT LANE **MERLIN OR 97532** 

085997

ESTIMATE (Valid for 30 days)

DATE 10 /31 / 07 SERVICE WILL CALL PHONE (S/O) SIT	7-8476
NAME  NAME	dez
ADDRESS MODEL	
G.P. SERIAL Gree	<b>^</b>
SENIAL V	
ITEM TO BE SERVICED NATURE OF SERVICE REQUEST	
QTY. PART # DESCRIPTION OF PARTS OR MATERIALS PRICE	AMOUNT
Repair druiers siele.	
Quarter panel (Rear)	
Rust repair	
Refabricate door	
hinge mount 2 body mes	
Weld inner plate	
weld outer panel	
Seal inner fenderwell	
(Rust 5top), 2 body lines	
LABOR PERFORMED Primer Sealer TOTAL MATERIALS	
Poduco-hardine	
ARREN WILLIAMSON'S AUTO BODY  TOTAL	
CUSTOMIZING	2
arren Williamson	1
TOTAL	440 00
eo Ort Lane erlin, Oregon 97532	1-7
	C
1-471-9323 shop WILL NOT BE RESPO 1-761-4283 cell R CAUSES BEYOND	OUR CONTROL,
DE POPLA APPO O ODEZIALIZES INTEGILLISTON WOLAS	PAIR ORDER
3 adams TEDMC NET CACH	ORIGINAL 5084



Sarvies that you can thest

shown above if I choose not to authorize the service recommended

EIGHBORHOOD AUTO CARE	TIME IN DATE
CODES	ORDER TAKEN BY:

RES. PHONE MODEL 300GD 8476 BUS. PHONE 3610 Gravenstein Huy 50 Sebastopol, CA 95472 80 Kai Tel 707 823-3832 Fax 707 823-3489 MAKE Har MILEAGE ENG. SIZE IGNITION STD. DELEC Pass 9757 Grants HOW DID YOU DISCOVER PRECISION TUNE AUTO CARE? REFERRAL REPEAT COUPON COSTS (PARTS & LABOR) NEWSPAPER DESCRIPTION REQ. YELLOW PAGES SIGN 0 (3) FLEET/CHARGE AIR COUPON (TYPE) (3) CCV BREATHER Ō 0 HOW DOES IT RUN? PCV VALVE HESITATES (A) IDLES HOUGHLY STARTS & DIES EXCESSIVE CRANKING FUEL STALLS NOL ENGINE OIL (E) (3) ALL PARTS NEW UNLESS OTHERWISE SPECIFIED TRANSMISSION SERVICE TRANSMISSION (A) (M) (A) TUNE UP TRANSFER CASE FILICARE CLEAN DIFFERENTIAL (F) (R) (3) TUNE UP MAINTENANCE (20) A/C - ALT - PS - A.P. RADIATOR SERVICE (3) (3) LUBE . OIL . FILTER SERPENTINE 0 (3) OTHER SERVICES DIAGNOSTIC TIMING BELT (IF APP.) (3) (3) AIR CONDITIONING RADIATOR CAP (3) 0 (3) RADIATOR HOSES (U) (L) (3) 3 VALVE ADJUSTMENT <u></u> HEATER HOSE © (F) EMISSION ADJUSTMENT COOLING SYSTEM FLUSH PH Ō (3) -65 -45 -34 -20 -10 FREEZE I HEREBY AUTHORIZE REPAIR WORK/SERVICE INCLUDING MATERIAL I GRANT PRECISION TUNE AUTO CARE EMPLOYEES PERMISSION TO OPERATE THE DESCRIBED VEHICLE ON PUBLIC ROADS FOR THE PURPOSE OF INSPECTION AND TESTING. I UNDERSTAND THAT A DIAGNOSTIC FEE OF \$25.00 WILL BE LEVIED IF THE VEHICLE IS UNTUNEABLE DUE TO MECHANICAL PROBLEMS. THIS FEE MAY BE APPLIED TO A TUNE-UP SERVICE WITHIN 30 DAYS AND UPON COMPLETION OF NECESSARY REPAIRS. AN EXPRESSED MECHANIC'S LIEN IS HEREBY ACKNOWLEGED ON THE DESCRIBED VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. (3) (E) SYSTEM SERVICE 0 (3) OUTLET TEMP (A) CABLES CORRODED 3 LOOSE (3) 3 BATTERY BATTERY CONDITION (3) (3) SECURE (3) @ CUSTOMER SIGNATURE BATTERY SERVICE Ē 8 CUSTOMER'S COMMENTS & REQUESTS ENGINE/SES 000 CHARGE/OIL PRESSURE (E) (2) BRAKES/ABS 0 8 DISTRIBUTOR CAP DO YOU WANT TO KEEP OLD PARTS? YES NO ROTOR 0 Ē WIRE LEADS SERVICE SUMMARY SMOG CHECK SPARK PLUGS 000000 000 CERTIFICATE PARTS LABOR TUNE-UP MAINTENANCE FAILED TUNE UP PASS ROTOR LIFETIME READING 000 DIST. CAP AFTER **FUEL INJECTION** PCV. AIR INDUCTION HC HC WIRES (E) DIAGNOSIS **FUEL FILTER** CO 3 BRAKE FLUID LEVEL "BY LAW, YOU MAY CHOOSE ANOTHER FACILITY TO PERFORM ANY NEEDED REPAIRS OF ANY NEEDED REPAIRS OF ANY NEEDES WHICH THE SMOG CHECK TEST INDICATES ARE NECESSARY." LOF 000000 BRAKE INSPECTION OIL 4 CV BOOTS AIR FILTER FLUID LEAKS TRANS LIGHTING INSPECTION VALVE ADJ SMOG CHK TIRE PRESSURE PRECISION TUNE AUTO CARE SMOG CERT (A) TIRE ROTATION YES RAD. SERVICE VC GASKET CERTIFIED BY FUEL S.S. VALVE ADJUSTMENT (4) WHEEL BALANCE 57 DIPO TECHNICIAN SAMPALIT AC Y LISTE SAME SEK SOK 150 500 TON SOK \*Suggested \*\*Required Acres 100 per Files Bir tue 6 AUTHOMIZED BY I IN PERSON VI PER RIDI ALE THE HEARING ADDITIONAL THERE DIMA TECH COMMENTS TOTAL PARTS TOTAL LABOR PAYMENT BY 90 30 J CASH 30 J CHECK SUBTOTAL TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within U VISA/MC FLEET SALES TAX

days of the date

OTHER

TOTAL



580 SEBARTOPOL ROAD SANTA ROSA, CA 95404 707-526-1987

006074

M	A	Tune SANTA	A ROSA 707-526-	, CA 9		CODE	=e	CODE	s	TIME OUT		TIME		
•	_					******	-5			ORDER TAKEN BY:		DATE		
	AM	100 No. 100 No	Vict	- 00		(FIRST)	m }	YR 80	MOD	300 GD	BUS. PHONE	510	- 517 -8	8476
	422	RESS (1777 M	idesa	1	Au	ZIP		LIC Mere		TION	ENG. SIZE		MILEAGE	
L		Grants	Pass				27	HOW DID YOU		STD. DELEC.	AUTO CARES			
L	-	DESCRIPTION		sugg.	REQ."	(PARTS & L	ABOR)	TV RADIO	DISCOVER	□ NE	WSPAPER LLOW PAGES	RE	FERRAL PEAT PEAT COU	PON
BS		CCV BREATHER	0		3			COUPON	YPE)	isid			EET/CHARG	
FILTERS		PCV VALVE	(3)	0	(3)			HOW DOES IT		S ROUGHLY	PINGS	HESITATE	ES	
NO	_	FUEL ENGINE OIL	0	<u> </u>	(3)			STARTS & DI			SURGES	XCESSI	VE CRANKING	3
CATIC		TRANSMISSION (A) (M)	0	8	8			TUNE UP	W UNLESS O	THERWISE SPECI	FIED TRANSM	ISSION	SERVICE	
LUBRICATION		DIFFERENTIAL (F) (R)	0000	000000000000000000000000000000000000000	3666666	· · · · · · · · · · · · · · · · · · ·			MAINTENAN	ICE [	FILICARE			
0		A/C - ALT - PS - A.P.	000	(a)	8			LUBE · OI	L·FILTER	[	RADIATO	R SER	VICE	
27 130		TIMING BELT (IF APP.)	0	0	8			DIAGNOS	TIC	[	OTHER S	ERVIC	ES	1
+	1	RADIATOR CAP	<u></u>	0	8			AIR COND	DITIONING					_
OH IOO		RADIATOR HOSES (U) (L)	0	0	@				DJUSTMENT					- 1
000	3	COOLING SYSTEM FLUSH PH			8			EMISSION	ADJUSTME	NT				
-		-65 -45 -34 -20 -10 FREEZE		0	88888888			COANT PREC	ICION TUNE	EPAIR WORK/SE	PLOYEES PER	RMISSI	ON TO OP	EPT-
1	AC	OUTLET TEMP°F	0		300			ATE THE DES	CRIBED VEH	ICLE ON PUBLIC 3. I UNDERSTAN THE VEHICLE IS	ROADS FOI	MAGNO	STIC FEE	OF
		CABLES CORRODED		<u>Ø</u> .	<u>®</u>			30 DAYS AND	MS. THIS FEE	MAY BE APPLIED	SSARY REPA	IRS. AN	EXPRESS	SED
DATTER		LOOSE BATTERY CONDITION	0	0	3			MECHANIC'S	LIEN IS HER	EBY ACKNOWLE	GED ON TH	E DES	CRIBED VE	EHI-
Na A	1	SECURE	<b>©</b>	000	333333			CUSTOMER SIGNATU	IRE C	<del></del>	DATE	1.1	4.0	14
Sd		BATTERY SERVICE ENGINE/SES	<u>©</u>	8	8	400		CUSTOMER'S	COMMENTS &	REQUESTS				
ND LAMPS	1	CHARGE/OIL PRESSURE BRAKESIABS	0	9	000									
E	-	DISTRIBUTOR CAP	00	00000000000	8			DO YOU WANT	TO KEEP OLD	PARTS?	ES NO	-		-/
1	1	ROTOR WIRE LEADS	0	8	8888888			- Swoo	CHECK	S	ERVICE SUM	MARY		=
	dn.	SPARK PLUGS	<u>©</u>	Ø.	0			CERTIF	FICATE		PARTS		LABOR	
	TUNE-UP	TUNE-UP MAINTENANCE	0	8	8			PASS	FAILED	TUNE UP ROTOR				
1		FUEL INJECTION	00	9	9			BEFORE	AFTER	PCV.				-
		AIR INDUCTION DIAGNOSIS	(3)						нс	WIRES FUEL FILTER				-/
		BRAKE FLUID LEVEL BRAKE INSPECTION	00	0	38888888			BY LAW, YOU ANOTHER FACILITY	MAY CHOOSE	LOF				
		CV BOOTS	0	0	00			ANOTHER FACILITY ANY NEEDED ADJUSTMENTS WH CHECK TEST IN NECESSARY.		OIL AIR FILTER				
1	SOON	FLUID LEAKS LIGHTING INSPECTION	8	8	8			NECESSARY.	DIOATES ARE	TRANS. VALVE ADJ.				
	LLANE	TIRE PRESSURE	6	0	(S)		******	PRECISION TUNI		SMOG CHK.				
	MISCELLANEOUS	TIRE ROTATION VC GASKET	9	90000000	36			CERTIFIED BY	Омо	SMOG CERT. RAD. SERVICE				
	1	VALVE ADJUSTMENT	0	3	0			Comment	-	FUEL S.S.				
		WHEEL BALANCE WIPERS	8	8	8		LAKEPT,	TECHNICIAN		7 ix	oic	1	icie	
1			45K (	SEI SOK	75K	90K				Tiv	11-1		170	
L	OR	BIGINAL AUTHORIZED BY	T FH VI		oy riskopsoza	-	] [*1171	*Suggested **I		7115	MEL		100	, ,
\$	100	IN PERSON	6	18	IN PERS		5	O IN PERSON						
Ri	ASC	COST	REASON	N		ACCETIONAL COST	FEARE		COST					
DA	TE.	TIME	DATE		T sta	s ne	GATE	TIME						
_		COMMENTS									-			
IEC	ri (	COMMENTS								PAYMENT BY:	TOTAL PA	ARTS	TOTALL	ABOR
	122-									☐ CASH		-		
										U CHECK	SUBTOTA	Ľ		
AR	DC	OWN ESTIMATE: I understar	nd that m	ny vehic	de will	be reassembl	ed within	day	s of the date	FLEET	SALES TA	×		
own	at	bove if I choose not to authori	ize the se	ervice r	ecomm	ieriueu.				OTHER	TOTAL		12	SIC

GARY SMERDON AUTOMOTIVE 3545 DEMARAY DRIVE

---- CUSTOMER ----GRANTS PASS, OREGON 97527 ---- VEHICLE ----4:24 PM (503) 474-2007 SYMPTOM : VICTOR, ALLEN & BLIZABETH SERVICE : LOF 4222 MIDWAY AVE. YR/MAKE: 1980 Mercedes 300Gd GRANTS PASS, OR 97527 LICENSE : SL 64567 (541)471-1019 VIN : 25,985 Date: 06/18/2007 Due Date: 06/18/2007 INVOICE NUMBER N30965 SL 64567 PAGE: 1 
 PARTS & LUBRICANTS USED
 QTY.
 PRICE
 TOTAL

 (MIK) 15W40 DELO OIL (GALLON)
 1.50 13.75 20.63

 (MIK) OIL PILTER CANISTER TYPE
 1 21.00 21.00
 COMMENTS & DESCRIPTION OF CHARGES\_ \_\_PRICE\_\_\_\_PARTS & LUBRICANTS USED\_\_\_ LABOR TO INSTALL PHONE JACK, CHECK TEMP GAUGE, FOUND BAD TEMP GAUGE (MIK) 68.00 68.00 | 7 SUBLET 0.00 SHOP SUPPLIES : 4.00 HAZ. DISPOSAL 0.00 This vehicle will be reassembled within 3 days of the date shown above if I do not authorize the recommended services. THANK YOU FOR YOUR BUSINESS SUB-TOTAL 113.63 TOTAL 113.63 BALANCE 113.63 ACCEPTANCE SIGNATURE Estimates Record TIME PHONE APPROVED BY TOTAL PARTS(add) LABOR(add) INCREASE CALLER REASON FOR ESTIMATE INCREASE 06/18/07 4:24P 471-1019 VICTOR, ALLEN & 113.63 41.63 68.00 original estimate

I authorize the above repairs and necessary materials. Your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or items left in it. I agree to pay reasonable storage on vehicle left more that 48 hours after notification that repairs are completed. An express Mechanics Lein is acknowledged on above vehicle to secure the amount of repairs thereto. Labor is guaranteed for 90 days or 4000 miles whichever occurs first. All other guarantees are those made exclusively by the manufacturer. Warranty work that is based on this repair order must be performed at this shop.

A L L R E M O V E D P A R T S W I L L B E D I S P O S E D O F U N L E S S I I N I T I A L H E R E

ALLKEMOVED PAKIS WILL BE DISPOSED OF UNLESS I INITIAL HERE\_\_\_\_\_.

the STATES STATES

321 S.E. "H" ST. GRANTS PASS, OR 97526 479-5333

DATE 6/2/0/ 10 44493

NAME

ADDRESS

CITY ZIP PHONE

YEAR MAKE/MODEL LIC. OR P.O.

LIST	NET	PARTS DESCRIPTION	LIST	NET
	2 (	mulffell		5000
	00	TAIL 0,00		4000
1	40)	Han ex		200
y disclaims all warranties, or fitness for the naticular		1	PARTS ->	1000
izes any other person to s and/or accessories g with necessary materials		<b>\</b>	LABOR →	- 50
on above vehicle to secure n collection of said lien.	^	LUICA DANYO DO		100
my for loss or gamage by r white road lesting.	, , , , , , , , , , , , , , , , , , ,	DEPOSIT HOA CASH, CHECK NO.	DRIVER'S LIC	CENSE NO. &
4 1	by are those made by the y disclaims all warranties, or fitness for the particular rizes any other person to a andior accessories. g with necessary materials, es of testing, inspectoon or on above vehicle or or advised from the same of the same o	by are those made by the y disclaims all warranties, or fitness for the particular (zes any other person to a and/or accessories g with recessary materials, es of testing, inspection or on above vehicle to secure in collection of said lien.  Which is to the collection of the collec	by are those made by the y disclaims all warranties or finess for the particular lizes any other person to a and/or accessories of the fing. Inspection or on above vehicle to secure or disclosion of taild lien.  CHG MC VISA PARTS ROA CASH CHECKED.	y are those made by the of declaration of sand the person to a radior accessory materials es of lesting, inspection or an above whole to secure or allow for the sand to accessory materials es of lesting, inspection or or above whole to secure or allow for the sand to access the

#### HENRYS FOREIGN AUTO SERVICE&SALES,INC. **4586 S.PACIFIC HWY** PHOENIX OREGON 97535

Ph. 541-535-1775 Fax: 541-535-4318

WWW.HENRYSAUTO.COM

(comp.1)

Slavek Krolak

Michael, Meeder

Mercedes300GDiesel

Customer: Address:

Victor, Kaiko

4222 Midway Ave. City, State: Grants Pass, OR 97527

Day Phone: 510-517-8476

Night Phone:

Fax:

Thermostat

Estimate Ref: 3061 Date: April 06, 2007 Time: 06:03 PM

Mileage:

VID:

Service Writer:

Service Tech:

21,038 Gelaende hagen (4x45leV)

Vehicle:

1982 Mercedes Benz 3000 (125 Chassis) L5-2998cc 3.0L DSL SOHC Turbo 617

Description	Part #/Labor Rate	Qty	Price/Time	Extended
VIN: 460 332 17 004769 model 460.3 2500kg 5 cylinder Diesel				
No turbo engine. Maual 4-speed transmission. Three doors SUV				
we used labor guide for engine work for Mercedes 300D sedan				
Remarks:				
Transmission output shaft is loose, shaft between transmission and				
transfer case has to be removed- adjust bearing, replace transf.				
case input shaft seal.				
Right front wheel bearing- too much play- need adjusting				
Play at the steering wheel- needs all tie rods, especially left and				
right rear part (three rod ends). After rod replacement, there still				
may be necessary to adjust gear box)				
Engine oil leak- engine oil filter case gasket				
Transfer case- output shaft bearing need adjustment (to rear				
driveshaft)				
Check for excessive white smoke, it was also difficult to start cold				
engine- cylinder head gasket leaks. Need thermostat.				
Drive/Propeller Shaft- shaft between transmission and transfer				
case				
Remove/ tighten transmission flange bolt (inspect bearing), replace transfer case input shaft seal (B)  Does Not Include: Flex Disc Replacement.	Labor 80.00 / hr	1	2.50	200.00
Transfer case input shaft seal - (supplied by customer)		1	0.00	0.00
Driveshaft/propeller shaft- between transfer case and rear	Labor 80,00 / hr	i	2.60	208.00
differential - remove parking brake, tighten transfer flange nut (inspect bearing)	E4001 60,007 III		2,00	208.00
Gear oil		1	10.00	10.00
Gear on			10,00	10,00
Adjust Right front wheel bearing	Labor 80.00 / hr	1	0.50	40.00
Tie Rod assembly - front and rear supplied by customer.	ranger out to the	2	0.00	0.00
Replace		**	0.00	0,00
One Side (B)	Labor 80,00 / hr	2	0.60	96.00
Does Not Include: Toe-In Adjust.	thous outout III		0,00	30,00
Front wheel alignment		1	75.00	75.00
Left front tire was leaking- the rim is corroded. Replace with the		i	20.00	20,00
spare rim. At this point the spare wheel will leak air. Rim has to		•	***************************************	20,00
be sandblasted, or replaced. Charge for tire change and balance.				
Oil filter case- remove/replace case-to-block gasket	Labor 80,00 / hr	1	2.00	160,00
Oil filter case gasket		1	3.40	3.40

ceplace (C)  oolant (for inspection before valve job)  Customer complains about smoke when started cold engine. Engine has to be cranked longer then usual. Warm up the engine, combustion gases enter cooling system. Needs cylinder head gasket, recommended is complete valve job- roughly estimate for complete work is @ \$2,000.00  Valve  Resurface/Grind (A)  Includes: R&R Cylinder Head And Make All Necessary  Adjustments.  Remarks: cylinder head was pressure tested in the machine shop-cylinder head has cracks. Cost of test:  Used Cylinder Head with big glow plugs  Machine shop- replace all valve guides, grind seats and valves, surface the head  Cylinder head gasket set  Valve stem seal kit  Valve guides - exhaust and intake, oversized	— th Gasket 80 Deg. Engine 617.912: to Series 12-067785	C1 C0000415	1	21.00	21.00
Customer complains about smoke when started cold engine. Engine has to be cranked longer then usual. Warm up the engine, combustion gases enter cooling system. Needs cylinder head gasket, recommended is complete valve job- roughly estimate for complete work is @ \$2,000.00  Valve  Resurface/Grind (A)  Includes: R&R Cylinder Head And Make All Necessary Adjustments.  Remarks: cylinder head was pressure tested in the machine shop-cylinder head has cracks. Cost of test:  Used Cylinder Head with big glow plugs Machine shop- replace all valve guides, grind seats and valves, surface the head Cylinder head gasket set Valve stem seal kit Valve stem seal kit Valve stem seal kit Valve guides - exhaust and intake, oversized Fuel injectors, rebuilt Fuel injector return lines Coolant Oil Filter Oil Filter Kit Hengst = DO3 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/IIX Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor 80.00 / hr  1 15.50 1240.00 1 240.00 1 13.50 125.00 1 2250.00 1 2250.00 1 25.00 1 25.00 1 25.00 1 25.00 1 25.00 1 25.00 1 25.00 1 25.00 1 26.00 1 24.00 1 25.00 1 2	Chlace (C)	6162000415			56.00
Customer complains about smoke when started cold engine. Engine has to be cranked longer then usual. Warm up the engine, combustion gases enter cooling system. Needs cylinder head gasket, recommended is complete valve job- roughly estimate for complete work is @ \$2,000.00  Valve  Resurface/Grind (A)  Includes: R&R Cylinder Head And Make All Necessary Adjustments.  Remarks: cylinder head was pressure tested in the machine shop-cylinder Head was pressure tested in the machine shop-cylinder Head whith big glow plugs  Used Cylinder Head with big glow plugs  Machine shop- replace all valve guides, grind seats and valves, surface the head gasket set  Valve stem seal kit  Valve stem seal kit  Valve guides - exhaust and intake, oversized  Valve guides - exhaust and intake, oversized  Valve guides - exhaust and intake oversized  Valve stem seal kit  Valve stem seal kit  Valve guides - exhaust and intake oversized  Valve stem seal kit  Valve guides - exhaust and intake oversized  1 125.00 125.00  7 20.00 225.00  Fuel injectors, rebuilt  Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265  Engine oil  Timing Chain  Parts Information  Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total  Parts Total	-Ollant (Co.)	Labor 80,00 / 1	13		6.00
Valve   Resurface/Grind (A)   Labor 80.00 / hr   1   15.50   1240.00	(for inspection before valve job)		0.5	12.00	0.00
Resurface/Grind (A)	combustion gases enter cooling system. Needs cylinder head gasket, recommended is complete valve job-roughly estimate for				
Resurface/Grind (A)	Valve				
Includes: R&R Cylinder Head And Make All Necessary   Adjustments.   1   50.00   50.00		1 -1 90 00 / 1-	- 1	15.50	1240.00
Adjustments.  Remarks: cylinder head was pressure tested in the machine shop-cylinder head has cracks. Cost of test:  Used Cylinder Head with big glow plugs Machine shop- replace all valve guides, grind seats and valves, surface the head Cylinder head gasket set Valve stem seal kit Valve guides - exhaust and intake , oversized Fuel injectors, rebuilt Fuel injector return lines Coolant Oil Filter Oil Filter Kit Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total  Sub-Total  5 0.00 50.00	Include A Dan Collins and Make All Make	Labor 80.007 n		10,00	
Remarks: cylinder head was pressure tested in the machine shop-cylinder head has cracks. Cost of test:   Used Cylinder Head with big glow plugs   1   300,00   300,00     Machine shop- replace all valve guides, grind seats and valves, surface the head   1   125,00   125,00     Cylinder head gasket set   1   27,00   27,00     Valve stem seal kit   1   27,00   27,00     Valve guides - exhaust and intake , oversized   10   8,00   80,00     Fuel injectors, rebuilt   1   15,00   15,00     Fuel injector return lines   1   15,00   225,00     Oil Filter Kit   1   15,00   15,00     Oil Filter Kit   6171800009   1   13,50   13,50     Collant   1   15,00   21,00     Oil Filter Kit   6171800009   1   13,50   13,50     Engine oil   7   3,00   21,00     Fuel injector return lines   2,5 hours. Labor time reduced with valve job:   Labor Total   2524,00     Sub-Total   3489,90     Sub-Total   3489,90					
Cylinder head has cracks. Cost of test :   Used Cylinder Head with big glow plugs   1   235.00   235.00     Machine shop- replace all valve guides, grind seats and valves, surface the head   1   125.00   125.00     Cylinder head gasket set   1   125.00   125.00     Cylinder head gasket set   1   127.00   27.00     Valve stem seal kit   1   27.00   27.00     Valve guides - exhaust and intake , oversized   1   15.00   15.00     Fuel injectors, rebuilt   1   15.00   15.00     Fuel injector return lines   2   12.00   24.00     Coolant   01   11.50   13.50     Collant   01   11.50   13.50     Oil Filter Kit   Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265   7   3.00   21.00     Engine oil   7   3.00   21.00     Timing Chain   Parts Information   0019973094   1   95.00   95.00     Parts Information   0019973094   1   1.80   144.00     With valve job:   Labor Total   2524.00     Parts Total   3489.90     Sub-Total   3489.90			1	50.00	50.00
Used Cylinder Head with big glow plugs  Machine shop- replace all valve guides, grind seats and valves, surface the head Cylinder head gasket set  Cylinder head gasket set  Valve stem seal kit  Valve guides - exhaust and intake , oversized Fuel injectors, rebuilt Fuel injector return lines Coolant Oil Filter Oil Filter Kit Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total  Sub-Total  303000 2335.00 235.00 235.00 235.00 235.00 235.00 235.00 235.00 235.00 235.00 24.00 27.00 28.00 29.00	Remarks: cylinder head was pressure tested in the machine shop-		1	20,00	
Sach Cylinder Head with big glow plugs   1   235.00   235.00	Cylinder head has cracks. Cost of test:			300.00	300.00
Machine shop- replace all valve guides, grind seats and valves, surface the head  Cylinder head gasket set  Valve stem seal kit  Valve guides - exhaust and intake, oversized  Fuel injectors, rebuilt  Fuel injector return lines  Coolant  Oil Filter  Oil Filter Kit  Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265  Engine oil  Timing Chain  Parts Information  Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total  Sub-Total  1 125.00 125.00 27.00 27.00 27.00 27.00 27.00 27.00 27.00 27.00 27.00 27.00 27.00 20.00 20.00 20.00 20.00 21.00 21.00 21.00 21.00 22.00 23.00 24.00 25.00 25.00 25.00 25.00 25.00 25.00 25.00 26.	Used Cylinder Head with big glow plugs		- 1		235.00
Cylinder head gasket set  Valve stem seal kit  Valve guides - exhaust and intake , oversized  Fuel injectors, rebuilt  Fuel injector return lines  Coolant  Oil Filter  Oil Filter Kit  Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265  Engine oil  Timing Chain  Parts Information  Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total  Parts Total  Sub-Total  1 27.00 27.00 27.00 28.00 20.00 20.00 20.00 21.00 24.00 24.00 24.00 24.00 24.00 24.00 24.00 24.00 24.00 24.00 25.00 24.00 25.00 25.00 21.00 25.00 2	Machine shop- replace all valve guides, grind seats and valves,			233.00	
Valve stem seal kit  Valve guides - exhaust and intake , oversized Fuel injectors, rebuilt Fuel injector return lines  Coolant Oil Filter Oil Filter Kit Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total  Sub-Total  27.00 27.			1	125.00	125.00
Valve guides - exhaust and intake , oversized Fuel injectors, rebuilt Fuel injector return lines Coolant Oil Filter Oil Filter Kit Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total  Sub-Total  10 8.00 80.00	Cylinder head gasket set		1		27.00
Valve guides - exhaust and intake , oversized  Fuel injectors, rebuilt Fuel injector return lines  Coolant  Oil Filter  Oil Filter Kit  Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel =  PF 1055/1X Bosch 1 457 429 265  Engine oil  Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total  Sub-Total  5 45.00 225.00  15.00  24.00  24.00  24.00  24.00  24.00  24.00  24.00  24.00  24.00  24.00  24.00  24.00  25.00  26.00  26.00  27 3.00 21.00  26.00  27 3.00  27 3.00  28 3.00  29 5.00  20 95.0					80.00
Fuel injectors, rebuilt Fuel injector return lines Coolant Oil Filter Oil Filter Kit Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total Parts Total Sub-Total  1 15.00 15.00 24.00 24.00 24.00 24.00 24.00 24.00 25.00 26.0					225.00
Coolant Oil Filter Oil Filter Kit Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total Parts Total Sub-Total  12.00 24.00 24.00 24.00 24.00 24.00 24.00 24.00 2524.00 2524.00 2524.00 2524.00 265.90 267.00 267.00 24.00 2524.00 2524.00 267.00					15.00
Oil Filter Oil Filter Kit Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel = PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total Sub-Total  Sub-Total  13.50					24.00
Oil Filter Kit     Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel =     PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total Parts Total Sub-Total  Sub-Total  13.30 13.30 13.30 21.00 21.00 21.00 21.00 25.00 95.00 95.00 25.400 965.90			2		
Oil Filter Kit     Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel =     PF 1055/1X Bosch 1 457 429 265     Engine oil     Timing Chain     Parts Information     Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:    Cabor Total Parts Total   Par	Oil Filter	**********	1	13.50	13.50
PF 1055/1X Bosch 1 457 429 265 Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:    Comparison   Content   Con		6171800009		13,50	
Engine oil Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total Parts Total Sub-Total  5.00 95.00 95.00 144.00  Labor Total 965.90  Sub-Total 3489.90	Hengst = D03 E196HN Knecht = OX 78D Mann-Hummel =				
Engine oil  Timing Chain  Parts Information  Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:    Labor Total   95.00   95.00	PF 1055/1X Bosch 1 457 429 265		7	3.00	21.00
Timing Chain Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:    Labor Total   95.00   95.00	Engine oil		,	5.00	
Parts Information Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor 80.00 / hr 1 1.80 144.00  Labor Total 2524.00 Parts Total 965.90  Sub-Total 3489.90		**********		95.00	95.00
Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:  Labor Total 2524.00 Parts Total 965.90  Sub-Total 3489.90	Parts Information				144.00
Parts Total   965.90	Replace (B) Regular time is 2.5 hours. Labor time reduced with valve job:	Labor 80.00 / III	•	****	
Parts Total 965.90  Sub-Total 3489.90			Labor Total		2524.00
Sup-10tal					965.90
£ 2490.00			C-b Total		3489.90
Total \$ 3489.90			Sub-10tai		
Total			Total		\$ 3489.90
THE OF THE PARKET IN THE PARKE					

# ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED!

I, the registered owner authorize you to perform the above repairs and furnish necessary materials. I understand that any cost quoted heretofore is an estimate only. You and your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. In the event any attorney is retained to bring suit for collection of any sums due, I agree to pay costs of collection and reasonable attorney fees. I also understand that the dealer is not a depository for personal property left in the vehicle and assumes no risk for loss thereof. If the vehicle described herein is not called for within three(3) days after such notice is given a storage charge of \$10.00 will be made for each day thereafter. I have read and understood the above.

THANK YOU!

5 of cash \$3,362.00 \$1000

Signature

cat Kit

Date

**HENRYS FOREIGN AUTO** SERVICE&SALES,INC. 4586 S.PACIFIC HWY **PHOENIX OREGON 97535** 

Ph. 541-535-1775

Fax: 541-535-4318

WWW.HENRYSAUTO.COM

Service Writer:

Service Tech:

VID:

Mileage:

(comp.1)

Slavek Krolak

Slavek Krolak

21,038

Mercedes300GDiesel

Customer: Address:

Victor, Kai

4222 Midway Ave

City, State: Grants Pass, OR 97527

Day Phone: 510-517-8476 Night Phone:

Vehicle:

Fax: Estimate Ref: 3061

Date: January 16, 2007 Time: 01:17 PM

30

30063

Gelande wagen

1982 Mercedes Benz 300D (123 Chassis) L5-2998cc 3.0L DSL SOHC Eartho 617

Description	Part #/Labor Rate	Qty	Price/Time	Extended
VIN: 466033217004769				
Charging System,				
Diagnose/Test (B)- alternator nor charging.	Labor 80.00 / hr	1	0.50	40.00
Includes: Test & Clean Terminals, Check Alternator				
Output, Regulator & Belt Tension, Inspect All. Cahles &				
Wiring.	* 1 00 00 (1-		1.00	80.00
Fix wiring problem with alternator- install extra wire from battery to alternator. Replace alternator voltage regulator	Labor 80.00 / hr	1	1.00	80.00
Voltage Regulator, Bosch				
Parts Information	0021545806	1	63.15	63.15
Part is Interchangable with Other Part Number(s). Bosch	0021545000		32.22	
1 197 311 090 use with 004 154 18 02 or.				
005-154-63-02 or 005-154-95-02				
Wire with connectors		1	2.00	2.00
Valve Clearance		-		100.00
Adjust (B)- remarks: valves were too tight, inspect timing	Labor 80.00 / hr	1	1.50	120.00
chain- OK Valve Cover Gasket				
Parts Information	6170160180	1	14.50	14.50
Fuel injector return hoses 3.2mm- set	3170100100	î	10.00	10.00
Fuel injector end plug		1	1.00	1.00
Check engine stop vacuum diaphram at fuel pump- OK.				
Check all lights, replace several light bulbs, clean connectors, etc.	Labor 80.00 / hr	1	0.50	40.00
Light bulbs		3	2.50	7.50
Remarks:				
Transmission output shaft is loose				
Right front wheel bearing- too much play				
Play at the steering wheel- needs all tie rods, especially left and right rear part				
Engine oil level is low				
Luguic on rever is ton				
	La	bor Total		280,00
	Pa	rts Total		98.15

Labor Total	280.00
Parts Total	98.15
Sub-Total	378.15
Total	\$ 378 15
Total	\$ 378.15

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED!

I, the registered owner authorize you to perform the above repairs and furnish necessary materials. I understand that any cost

chech # 40 4



P.O. BOX 729
4104 W. WHITE RD., SUITE 101
OAKWOOD, GA 30566 USA
TEL (770) 965-3311 (678) 414-6647
FAX (678) 960-0032
www.eurotruck-importers.com

# INVOICE

Date 2/7/2007 INVOICE # 2626

Bill To

Kaikoo Victor 4222 Midway Ave Grants Pass, OR 97527 Ship To

Kaikoo Victor 4222 Midway Ave Grants Pass, OR 97527

Part Number	Description	Ordered	Shipped	Each	Price
A 463 463 0015 A 460 330 0703 A 007 997 7647 A 007 997 8147 A 000 992 1010 A 210 992 0010 Shipping	DRAG LINK TIE ROD ASSEMBLY SEAL RING SEAL RING BUSHING BUSHING SHIPPING	1 1 3 1 3 3	1.00 1.00 3.00 1.00 3.00 3.00	238.50 425.50 24.60 50.65 3.63 2.31 20.28	238.50T 425.50T 73.80T 50.65T 10.89T 6.93T 20.28

THANK YOU FOR YOUR BUSINESS!	Subtotal	\$826.55
NO RETURNS WITHOUT RETURN AUTHORIZATION NUMBER 15% RESTOCKING CHARGE ON RETURNED PARTS	Sales Tax (0.0%)	\$0.00
NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS	Total	\$826,55

HENRYS FOREIGN AUTO SERV 4586 S PACIFIC HWY PHDENIX, OR. 97535 541-535-1775

Sale

ID: 0010548520000006070300 05/07/07 17:45:26

VISA

Inv#: 000001 Appr Code: 016452 \$ 225.00 Total:

Customer Copy

HENRYS FOREIGN AUTO SERVICE&SALES,INC. 4586 S.PACIFIC HWY PHOENIX OREGON 97535 Ph. 541-535-1775

Fax: 541-535-4318

WWW.HENRYSAUTO.COM

Service Writer: Service Tech:

Slavek Krolak Slavek Krolak

(comp.1)

VID:

Mercedes300GDVac.Pump

24,509

Mileage:

THANK YOU!

Vehicle:

1982 Mercedes Benz 300D (123 Chassis) L5-2998cc 3.0L DSL SOHC Turbo 617

Description	Part #/Labor Rat	e Qty	Price/Time	Extended
VIN: 460 332 17 00 4769 5 cyl. diesel SUV				
Vacuum Pump Overhaul kit		1	55.00	55.00
Replace (B)	Labor 85.00 / hr	1	2.00	170.00
	L	abor Total		170.00
	P	arts Total		55.00
	Si	ub-Total		225.00
				•
	T	otal		\$ 225.00

#### ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED!

I, the registered owner authorize you to perform the above repairs and furnish necessary materials. I understand that any cost quoted heretofore is an estimate only. You and your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. In the event any attorney is retained to bring suit for collection of any sums due, I agree to pay costs of collection and reasonable attorney fees. I also understand that the dealer is not a depository for personal property left in the vehicle and assumes no risk for loss thereof. If the vehicle described herein is not called for within three(3) days after such notice is given a storage charge of \$10.00 will be made for each day thereafter. I have read and understood the above.

THANK YOU!

Signature	Date

#### Service Check List

Pre-Service Oil level: OVER 1 QUART LOW Check List	ce, humbly, with a servant's heart. "  Status
SECONDARY SEAL	
1.0 NO SECONDARY SEAL/FILTER STUD TIGHT (CESAR HERRERA)	CONFIRMED
DOWNSTAIRS CALL	
1.0 RUBBER GROMMET AND CHASSIS LUBE	COMPLETE-NO FITTINGS
2.0 DRIVELINE FITTINGS	VEHICLE NOT EQUIPPED- N/A
3.0 C.V. BOOT INSPECTION	VEHICLE NOT EQUIPPED- N/A
4.0 BRAKE ADJUSTMENT PLUGS	GOOD
5.0 OIL SEALS	SEEPING- EXACT SOURCE UNKNOWN
ENGINE OIL FILL	
1.0 NEW ENGINE OIL LEVEL CONFIRMED/SHOWN	LEVEL CONFIRMED/SHOWN
EXCELLENCE CHECK	CONFIRMED TIGHT #P825
1.0 OIL FILTER	dipstick
2.0 AUTO TRANS. CHECK/FILL PLUG	NOT EQUIPPED
3.0 AUTO TRANS. DRAIN PLUG	NOT EQUIPPED
4.0 AUTO TRANS. PLUG TORQ	NOT OPENED
5.0 COOLING SYSTEM DRAIN	14 MM HEX
6.0 OIL PAN DRAIN PLUG(S)	20 FT/LBS
7.0 OIL PAN DRAIN PLUG(5) TORQ	14 MM HEX
8.0 FRONT DIFF CHECK FILL PLUG	NOT EQUIPPED
9.0 FRONT DIFF DRAIN PLUG	14 MM HEX
10.0 MANUAL TRANS. CHECK FILL PLUG	
12.0 MANUAL TRANS. DRAIN PLUG	14 MM HEX
14.0 TRANSFER CASE CHECK FILL PLUG	14 MM HEX
15.0 TRANSFER CASE DRAIN PLUG	14 MM HEX
16.0 REAR DIFFERENTIAL CHECK FILL PLUG	17 MM HEX
17.0 REAR DIFFERENTIAL DRAIN PLUG	NOT EQUIPPED
OIL FILTER	
2.0 OIL FILTER INSPECTION	CONFIRMED AND LUBRICATED #P825
PLUG AND SEAL	
1.0 OIL PAN DRAIN PLUG	GOOD
2.0 OIL PAN PLUG SEAL	GOOD
3.0 PT15 ENGINE TREATMENT	ENGINE TREATMENT RECOMMENDED
SAMPLE CARD	
1.0 FRONT DIFFERENTIAL FLUID	FLUID SERVICED
2.0 MANUAL TRANSMISSION FLUID	NEEDS TO BE CHANGED- FULL
3.0 TRANSFER CASE FLUID	UNABLE TO CHECK, GUEST NOTIFIED
4.0 REAR DIFFERENTIAL FLUID	FLUID SERVICED
SERVICE COORDINATOR ITEMS	
1.0 COLLATERAL MATERIAL	INSTALLED /GIVEN
4.0 O - COOLING SYSTEM PRESSURE CHECK	HOLDING PRESSURE
6.0 O - COOLANT/ANTIFREEZE PROTECTION LEVEL	-34 F
7.0 O - COOLANT/ANTIFREEZE FLUID LEVEL	GOOD
	NOT DUE
8.0 O - COOLANT/ANTIFREEZE STATUS	DEFECTIVE
9.0 O - WINDSHIELD WASHER FLUID	WINDOWS COMPLETED
10.0 CLEAN WINDSHIELDS FRONT AND REAR	GUEST OK-GOOD
11.0 CHECK WIPER BLADES	COMPLETED
12.0 LUBRICATE LOCKS LATCHES AND HINGES	NOT CHECKED
13.0 FRONT TIRE PRESSURE CHECK	NOT CHECKED
13.5 REAR TIRE PRESSURE CHECK	ON AND TIGHT
4.0 VALVE CAPS	
ERVICE WRITER ITEMS	NO CL SERVICE
2.5 COOLING SYSTEM SERVICE	LEVEL 1- GOOD
4.0 AIR FILTER RECOMMENDATION	
5.0 BREATHER FILTER REPLACEMENT	VEHICLE NOT EQUIPPED- N/A
6.0 PCV SMOG VALVE REPLACEMENT	NOT APPLICABLE
6.5 CABIN AIR FILTER INSPECTION	VEHICLE NOT EQUIPPED- N/A
7.0 BRAKE FLUID CHECK	GOOD-NOT FILLED
8.0 CLUTCH FLUID CHECK	GOOD - NOT FILLED
9.0 POWER STEERING FLUID LEVEL CHECK	VEHICLE NOT EQUIPPED- N/A
10.0 POWER STEERING LEAKAGE CHECK	NOT EQUIPPED
11.0 UPPER / LOWER RADIATOR HOSES- VISUAL INSPECTION	GOOD
	GOOD
12.0 DRIVE BELT INSPECTION	SEALED/MAINTENANCE FREE
14.0 BATTERY ACID LEVEL CHECK 15.0 BATTERY TERMINALS CLEANED AND PROTECTED	COMPLETED
15.0 BATTERT TERMINALS CLEANED AND PROJECTED	TECHRON RECOMMENDED
	TECHNON RECONSTRUCTOR
16.0 FUEL SYSTEM CLEANER 17.0 CAPS AND DIPSTICKS CHECK	TIGHT

# OILSTOP® DRIVE THRU DIL CHANGE



2210 ASHLAND ST ASHLAND, OR 97520 (541) 201 0700

#### **Guest Information**

Guest: MR. KAI VICTOR
Address: 4222 MIDWAY AVE

**GRANTS PASS, OR 97527** 

Phone: (510) 517 8476

E-Mail: KAIKOO@EXCITE.COM

Driver: MR. KAI VICTOR

# Service Notes

1. \*\* OILSTOP PRIVACY POLICY \*\* OILSTOP DOES NOT SHARE YOUR PERSONAL OR VEHICLE INFORMATION (NAME, ADDRESS, PHONE NUMBER, EMAIL, AND SERVICE HISTORY) WITH ANY THIRD PARTY

2. AUTOMATIC TRANSMISSION FLUID SERVICE RECOMMENDED. (BASED ON YOUR VEHICLES MILEAGE INTERVAL)

 WINDSHIELD WASHER FLUID RESERVOIR LEAKING-REPLACEMENT RECOMMENDED.

4. PRESENT THIS INVOICE FOR A FREE CAR WASH AT THE MEDFORD CENTER CAR WASH BEHIND SEARS ON STEVENS. (\$8.00 VALUE)

#### Service Information

Work Order #: F-0013-35758

Service Completed: JAN 18, 2007 5:58 PM

Service Coordinator: SEAN ROLAND
Service Writer: BOB LEWIS

Lube Technican: CESAR HERRERA
Manager: SEAN ROLAND

#### **Guest Auto Information**

c #: SL64567 Last Service

Year: 1980 Make: MERCEDES BENZ

Mileage: 21196 Model: 300D

Engine: 3.0L, 5-CYL CODE 617.912 EFI

OIL: CH 5/40 SYNTHETIC Tire Pressure: F ... P ...

VIN#:

Purchase Det	ail	
Service Name	Qty	Ext. Price
33 -POINT SERVICE FRONT DIFFERENTIAL SERVICE - 80/90GL5 HAZARDOUS WASTE DISPOSAL REAR DIFFERENTIAL SERVICE - 80/90GL5LS 80/90 GL5LS - 80/90 GL5LS 80/90 GL5LS - 80/90 GL5LS P825 - OIL FILTER #P825 CS540 - CH 5/40 SYNTHETIC	1 ea 1 ea 1 ea 1 ea 4 pounds 5 pounds 1 each 7 quarts	\$ 31.99 \$ 36.99 \$ 1.99 \$ 35.77 \$ 0.00 \$ 6.99 \$ 42.00

Sub Total: Tax:	\$ 155.73 \$ 0.00
Total:	\$ 155.73
Payment ( CC ):	\$ 155.73

\$ 0.00

# Thank you for letting us serve you today!

Change:

By signing below, you acknowledge that you were shown your engine oil dipstick at the completion of your service with the fill on the "Full Mark."

3 Kummun ( pt t

#### OILSTOP Commitment

- We will treat all people with the highest level of kindness and respect.
- 2. To create an outstanding service experience.
- To keep your car fully dependable for you to use and enjoy.
- 4. To lower your overall maintenance and repair cost.
- When you sell your car, you will feel confident, even if you sell it to your best friend.

#### WARRANTY

- OILSTOP warrants that all parts and materials used on your vehicle will meet or exceed your car's manufacturer's specifications and satisfy your car's warranty requirements.
- OILSTOP warrants the service performed on your vehicle to your satisfaction or we will completely re-perform the service at no charge.

# Get a FREE \$8.00 "Super Wash" with our thanks!



- / All cloth wash
- / Wheelbrite
- ✓ Clear coat shine
- Spot free drying system

Redeemable at Oilstop Car Wash 775 Mediord Center, Mediord 858-0226 Open 7 days 8-6



# Did you know . . .

We will electronically set your tires to the precise amount of inflation recommended by your vehicle's manufacturer.

Because, according to the National Highway Traffic Safety Administration, one in every 4 cars on the road today has at least one tire that is dangerously underinflated!

For your family's safety and your car's dependability, every little thing is important at Oilstop.

or you cliebus its branch shall the states affect that will be the an other after the Dechmician programs computerized the seek Couper has so used whose computerized the programs of accountedly set a guest's tire pressure



P.O. BOX 729 4104 W. WHITE RD., SUITE 101 OAKWOOD, GA 30566 USA (678) 960-0032 www.eurotruck-importers.com TEL (770) 965-3311 (678) 414-6647

## INVOICE

1808 **INVOICE#** 5/22/2006 Date

Bill To

Sidney Hoyt Copeland 2394 Lower Gabriel's Rd Mars Hill, NC 28754

Ship To

Sidney Hoyt Copeland 2394 Lower Gabriel's Rd Mars Hill, NC 28754

Part Number	Description	Ordered	Shipped	Each	Price
A 123 180 0265 Shipping	OIL COOLER SHIPPING	1	1.00	363.00 9.83	363.00T 9.83T

Subtotal \$372.83 THANKS FOR YOUR BUSINESS! NO RETURNS WITHOUT COPY OF INVOICE Sales Tax (0.0%) \$0.00 15% RESTOCKING CHARGE ON RETURNED PARTS NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS Total \$372.83 NO REFUNDS AFTER 30 DAYS



P.O. BOX 729
4104 W. WHITE RD., SUITE 101
OAKWOOD, GA 30566 USA
TEL (770) 965-3311 (678) 414-6647
FAX (678) 960-0032

www.eurotruck-importers.com

# INVOICE

Date 5/10/2006 INVOICE # 1765

Bill To

Sidney Hoyt Copeland 2394 Lower Gabriel's Rd Mars Hill, NC 28754

Ship To		

Part Number	Description	Ordered	Shipped	Each	Price
A 617 180 0009	OIL FILTER KIT	1	1.00	10.11	10.11T
A 001 477 6601	FUEL FILTER	1	1.00	3.75	3.75T
A 002 094 2304	FILTER	1	1.00	73.84	73.84T
A 001 092 0401	DIESEL FUEL FILTER, SPIN ON	1	1.00	8.95	8.95T
A 004 997 9992	FAN BELT 12.5x1145	1 1	1.00	10.00	10.00T
A 005 997 6992	FAN BELT 12.5x1030	1 1	1.00	32.45	32.45T
A 460 500 0075	HOSE	1 1	1.00	109.76	109.76T 18.87T
A 460 832 1823	HOSE	1	1.00	18.87 20.87	20.87T
A 115 831 1094	HOSE DIESEL RETURN TO ENGINE SHIPPING	The state of	1.00	11.41	11.41T
Shipping					
				I	

Thanks for your business!	Subtotal	\$300.01
We now accept VISA, Mastercard and American Express for your convenience.	Sales Tax (0.0%)	\$0.00
	Total	\$300.01



4104 W. WHITE RD., SUITE 101 OAKWOOD, GA 30566 USA TEL (770) 965-3311 (678) 414-6647 www.eurotruck-importers.com

# INVOICE

**INVOICE#** 1859 6/15/2006 Date

Bill To

Sidney Hoyt Copeland 2394 Lower Gabriel's Rd Mars Hill, NC 28754

Ship To

Sidney Hoyt Copeland 2394 Lower Gabriel's Rd Mars Hill, NC 28754

P.O. BOX 729

Part Number	Description	Ordered	Shipped	Each	Price
A 617 180 0482 A 460 832 1494 Shipping	HOSE HOSE SHIPPING	1 1	1.00	132.00 29.29 6.53	132.00T 29.29T 6.53T

THANKS FOR YOUR BUSINESS!	Subtotal	\$167.82
NO RETURNS WITHOUT COPY OF INVOICE 15% RESTOCKING CHARGE ON RETURNED PARTS	Sales Tax (0.0%)	\$0.00
NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS NO REFUNDS AFTER 30 DAYS	Total	\$167.82

The Organic Mechanic 631 Haywood Road Asheville, NC. 28806 Phone - 828-255-2628 Fax - 828-255-2632

INVOICE

94

Org. Est. # 000364

Work Completed Date: 06/20/2006

Print Date: 06/30/2006

1980 Mercedes-Benz - G Wagon

oton

Lic#: Unit#:

Vin#:

Odometer In:

17, WU K. oretus

		Ref#:		Hat #:	
Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
Recore Radiator				Replace Oil Cooler	68.17
XXXXXX	1.00	493.17	493.17	Replace Oil Cooler, Top off with oil and check for	
ANTI-FREEZE COOLANT				leaks.	
Coolant	1.00	17.98	17.98	Oil Cooler Line'	27.27
Shop Supplies		3.00	3.00	Replace Lower Oil Cooler Line	
				RADIATOR HOSE - Remove & Replace - Lower	81.80
				ALTERNATOR DRIVE BELT - Remove &	61.35
				Replace - [Includes: Serpentine type.]	
				Comprehensive Maintenance Inspection	24.95
				1.A visual inspection of your vehicle's general	
				condition 2. Cranking and starting 3. Running	
				quality (idle, hesitation, misfire and noises) 4. Horn,	
				headlights, brake lights, turn signals, wipers, tail	
				lights 5. Electrical system, battery state of charge,	
				alternator charging voltages 6. Cooling System,	
				coolant level, leaks 7. Hoses and Belts 8. Power	
				Steering 9. Engine Oil level and condition 10.	
				Transmission Oil level and condition 11. Tire	
				condition and pressure 12. Steering and Suspension	
				13. Drive Axles 14. Brake Condition 15. Exhaust	
				Replace Radiator	129.52
				Cut Radiator Mounting Bracket Bolts Off Remove	
				And Replace Radiator With New Bolts Refill	
				Radiator And Purge Air	
				Fuel Filter Air Filter	129.52
				Replace Air Filter And Fuel Filter And Purge Air	
				Oil Change	13.63
				Oil Change	

The Organic Mechanic 631 Haywood Road Asheville, NC. 28806 Phone - 828-255-2628 Fax - 828-255-2632

	INVOICE	
	94	
Org.	Est. # 000364	

			Completed Date: 06/20/2006		e: 06/30/2006
			1980 Mercedes-Benz - 0	3 Wagon	
opeland, Sidney	Leslie Wooton		11-11-	Odomete	or In ·
394 Lower Gabriel's Re	oad		Lic#:	Odomete	: 111 .
Mars Hill, NC 28754			Unit#:		
lome 828-713-4999		Ref#:	Vin # :		
Cust ID :  Part Description / Numb		Sale Extended	Hat # : Labor Description		Extende
			12.5		
Technicians : Please Select Org. Estimate \$68.17	t, Technician; Wilson, Ch Revisions \$0.00	arley; Marshall, Shane  Current Estimate \$ 68.	17 Additional Cost Revise	d Estimate Labor:	
1			17 Additional Cost Revise	Laboi.	\$536.21 \$514.15 \$0.00 \$1,050.36  \$35.78 \$1,086.14

one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of

Page 2 of 2

Date...... Time.....

03.22.06 Invoic1

SIGNATURE.....

Written By: Wilson, Charley

Rear rear rocker = 149.00 A 460 640 01 71 rear left @ [] A 460 647 13 07 139.00 rear right [5] A 460 647 14 07 139.00 Sides : SA 59 085 00003 150 05 09 jest 110 best A460 630 50 21 right \$ 460 630 49 21 319.00 A 460 880 Z1 06 Front left fender from right fende 90 22 088 096 Y A 0005 545 31 24 Blinker Arm A 460 540 0047 insrument duster A 460 520 0042 engine potective D 000 869 30 21 Windshield Pump